

















INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE













- a service by drom























ECO INSPECTION REPORT

121+ Checkpoints Doorstep Inspection Service







Bajaj Platina 2007, 100cc




Vehicle Information

Make	Bajaj	Registration Type	Private
Model	Platina	Registration No.	MH12DZ8694
Year	2007	VIN/Chassis Number	Md2dddzzzpwa05471
Trim	100сс	Engine No.	Dumpba41354
Color	Black Crom	Manufacturing Date	2007-4-1
Fuel Type	Petrol	Registration Date	2007-5-9
Odometre Reading	76991	Insurance Expiry	2018-2-10
Engine CC	100	Location	Pune
No. of Owners	1	Engine Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	No	Insurance Copy Available	No	
Tyre Life Remaining(kM)	10000	Service Logs Available	Partial	
Dents/Scratches	Yes	Bank Hypothecation	No	
Major Accidents	NA	Bank NOC	NA	
RC Copy Available	Duplicate	Permit Valid	NA	
PUC Certificate Valid	NA			

ECO Score and Repair Estimates
























VEHICLE BODY

Vehicle Body View and Condition






















Generated: 10 Feb 2023


Additional Checkpoints




Vehicle Body Images



























Generated: 10 Feb 2023

HANDLEBAR & CONTROL


Handlebar & Controls View and Condition



Additional Checkpoints



Handlebar & Control Images

























Generated: 10 Feb 2023

LIGHTINGS and SWITCHES


Lightings & Switches View and Condition



Additional Checkpoints



Lightings & Switches Images



























Generated: 10 Feb 2023


Wheels

Wheels View and Condition



Wheel Images



























TEST DRIVE AND PERFORMANCE

Mechanical Parts & Oils Performance View and Condition



Additional Checkpoints























Generated : 10 Feb 2023


Mechanical Parts & Performance Images







Documents
























NEED ATTENTION


Light










Chassis
































Performance
























Other Images











































Other Images

FOG LAMP WORKING







CHASSIS FRONT COWL

CHASSIS BASE FRAME







CHASSIS LH COWL








CHASSIS REAR MUDGUARD

























Other Images

CHASSIS FRONT SEAT CONDITION







FRONT TIRE CONDITION & AIR PRESSURE







WHEEL RIM REAR







TEST ACCELERATION PERFORMANCE





















Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology Limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.





























