

# ECO INSPECTION REPORT

Premium

Order ID : 21830


ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Anuj | Inspection Date : 2018-08-19 | Valid Till : 2018-11-19

**6/10**  
 Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 115 does not need attention
- ✓ 2 Owners , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By

  
**Lokesh Kumar**

- ✓ Verified Technician
- 46+ vehicle inspected
- 1+ years experience

## Ford Figo Duratorq Diesel Exi 1.4, 2012



VEHICLE INFORMATION			
MAKE	FORD	TRANSMISSION TYPE	MANUAL
MODEL	FIGO	REGISTRATION NO.	DL10CF0819
YEAR	2012	VIN/CHASIS NUMBER	K89701
TRIM	DURATORQ DIESEL EXI 1.4	KMS RUN	60995
COLOR	BLACK	INSURANCE EXPIRY	2018-10-18
BODY TYPE	HATCHBACK	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	6,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO


 Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,12,158**

 Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 0	
Interior	<div style="width: 60%;"></div> 6 / 10	Interior	0
Wheel	<div style="width: 60%;"></div> 6 / 10	Wheel	0
Test Drive	<div style="width: 60%;"></div> 6 / 10	Test Drive	0
Exterior	<div style="width: 60%;"></div> 6 / 10	Exterior	0
Hood	<div style="width: 60%;"></div> 6 / 10	Hood	0

Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score  **6/10**





**2,12,158**

## INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	FAIR	0
PEDALS	6	FAIR	0
CENTRAL LOCK	6	FAIR	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	FAIR	0
HAZARD LIGHT	6	FAIR	0
NAVIGATION (NO)	0	NO	0
ODOMETER	0	FAIR	0
POWER WINDOWS (YES - FRONT ONLY)	0	FAIR	0

## IMAGES



Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score  **6/10**




**2,12,158**

## TEST DRIVE

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GIID	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
ENGINE NOISE	0	MINOR	0
REAR PARKING SENSORS (YES)	0	FAIR	0
REAR VIEW CAMERA (NO)	0		0

## IMAGES




## WHEEL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE (YES)	6	AVERAGE	0
WHEEL ASSEMBLY	6	AVERAGE	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	6	AVERAGE	0
ENGINE OIL	6	AVERAGE	0
COOLANT LEVEL	6	AVERAGE	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score  **6/10**



**2,12,158**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	MINOR SCRATCH, FULL PAINTED	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	6	FAIR	0
HOOD	6	FAIR	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	MINOR SCRATCH, FULL PAINTED	0
LH FRONT DOOR	6	MINOR SCARTCH, FULL PAINTED, MINOR RUST	0
LH REAR DOOR	6	SCARTCH, FULL PAINTED, MINOR RUST	0
LH RUNNING BOARD	6	SCRATCH, FULL PAINTED	0
LH QUARTER PANEL	6	FAIR.	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
REAR BUMPER	6	FULL PAINTED, MINOR SCARTCH	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
RH QUARTER PANEL	6	FAIR, MINOR PAINTED	0
RH RUNNING BOARD	6	SCARATCH, FULL PQINTED	0

RH REAR DOOR	6	FULL PAINTED	0
--------------	---	--------------	---

Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score



6/10



2,12,158



## EXTERIOR (CONTINUED)




6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	FULL PAINTED	0
RH FENDER	6	FULL PAINTED, SCRATCH	0
BODY RUST	6	RUST	0
ROOF (REGULAR)	6	FAIR	0
PAINT CONDITION	6	FAIR	0



## IMAGES



## DOCUMENTS



## DESCRIPTION

1 most part dent paint 2 pollution minor 3 engine good 4 3 tyre fair condition 2 2 tyre good condi



Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score




6/10



2,12,158

IMAGES





Ordered by: Anuj | Inspected date: 2018-08-19

Order Id: 21830

Overall Score



6/10



2,12,158

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.