




ECO INSPECTION REPORT Premium

Order ID : 22222






ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Jatin	Inspection Date : 2018-09-01	Valid Till : 2018-12-01	 Inspected By  Verified Technician 346+ vehicle inspected 1+ years experience Santosh Kumar
-----------------------	---------------------------------	----------------------------	---

6/10



Overall Score

-  Evaluated across 5 segments
-  Covered 121+ checkpoints
-  89 does not need attention
-  1 Owner , 5 Years Vehicle Age
-  No Accidental History

Maruti Suzuki Alto 800 Lxi Cng, 2013



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	ALTO 800	REGISTRATION NO.	DL2CAP9851
YEAR	2013	VIN/CHASIS NUMBER	214989
TRIM	LXI CNG	KMS RUN	85858
COLOR	SILVER	INSURANCE EXPIRY	2018-8-23
BODY TYPE	HATCHBACK	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	22,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:






1,85,878




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 60%;"></div>	6 / 10
 Exterior	<div style="width: 40%;"></div>	5 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 41,000



Category	Estimate
Interior	3,000
Wheel	0
Test Drive	5,500
Exterior	32,500
Hood	0

Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score



6/10



1,85,878



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
HANDBRAKE	6	GOOD	0
PEDALS	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
ODOMETER	6	GOOD	0
HAZARD LIGHT	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	0	VERY BAD	3000
STEERING-MOUNTED CONTROLS	5	GOOD	0
CENTRAL LOCK	0	NO	0
NAVIGATION (NO)	0	NO	0
POWER WINDOWS (NO)	0	NO	0



IMAGES



Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score 6/10




1,85,878

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
SUSPENSION PERFORMANCE	3	BAD	5500
CRUISE CONTROL (NO)	0	NO	0
REAR PARKING SENSORS (NO)	0		0
REAR VIEW CAMERA (NO)	0		0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY	6	GOOD	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0
COOLANT LEVEL	5	GOOD	0
UNDERCARRIAGE	5	AVERAGE	0

 IMAGES



Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score



6/10



1,85,878

 EXTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
PILLAR	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	5	PAINTED	0
TURN SIGNAL	4	RIGHT SIDE INDICATOR NOT WORKING	500
FOG LAMPS	0	NO	0
HOOD	3	ACCIDENT	8000
FRONT WINDSHIELD	3	BROKEN	4000
LH FENDER	5	PAINTED AND MINOR SCRATCH	1000
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED AND SCRATCH	2500
LH RUNNING BOARD	3	MINOR ACCIDENT	5000
LH QUARTER PANEL	5	PAINTED AND SCRATCH	2500
FUEL LID	5	PAINTED	0
REAR BUMPER	5	MINOR SCRATCH	0
TAIL LIGHT	3	BROKEN	3000
TRUNK LID/TAIL GATE	5	PAINTED	0
LUGGAGE COMPARTMENT LIGHT	4	NO SPECE CNG AVAILABLE	0
RH QUARTER PANEL	5	PAINTED AND MINOR SCRATCH	0

Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score



6/10



1,85,878



EXTERIOR (CONTINUED)




5/10








INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH RUNNING BOARD	5	PAINTED	0
RH REAR DOOR	5	DENT AND SCRATCH	2500
RH FRONT DOOR	5	SCRATCH AND PAINTED WIDING NOT AVAILABLE	3500
RH FENDER	5	PAINTED	0
PAINT CONDITION	5	ALL CAR IS PAINTED	0



IMAGES





NEED ATTENTION





 DOCUMENTS



 DESCRIPTION

car is all painted frant side accident Engine is average candition

Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score




6/10



1,85,878

IMAGES



Ordered by: Jatin | Inspected date: 2018-09-01

Order Id: 22222

Overall Score



6/10



1,85,878

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.