

ECO INSPECTION REPORT


Premium

Order ID : 22293

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Manik	Inspection Date : 2018-08-27	Valid Till : 2018-11-28
-----------------------	---------------------------------	----------------------------


6/10



Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 111 does not need attention
- ✔ 1 Owner , 5 Years Vehicle Age
- ✔ 4 Accidental History Reported

Inspected By



✔ **Verified Technician**



74+ vehicle inspected
1+ years experience

Lokesh Kumar

Hyundai Verna 1.6 Crdi Ex, 2013



VEHICLE INFORMATION			
MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	VERNA	REGISTRATION NO.	DL8CZ5888
YEAR	2013	VIN/CHASIS NUMBER	129483
TRIM	1.6 CRDI EX	KMS RUN	120919
COLOR	SILVER	INSURANCE EXPIRY	2018-6-8
BODY TYPE	SEDAN	LOCATION	GURGAOW
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	YES	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (3RD PARTY)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






4,07,696




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Test Drive	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10

TOTAL ESTIMATE SPEND 20,000



Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score



6/10



4,07,696



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	RUST.	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR	0
HORN	6	FAIR	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	NOISE.BOTH SIDE	10000
PEDALS	6	FAIR	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	6		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0



IMAGES



Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score



6/10



4,07,696



TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	NOISE	10000
BRAKE PERFORMANCE	6	FAIR	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	YESS	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (NO)	6		0
REAR PARKING SENSORS (YES)	6		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY	6		0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	6	FAIR	0
ENGINE OIL	6	AVERAGE	0
COOLANT LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAUR	0

 IMAGES



Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score  **6/10**



4,07,696

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED ,SCRATCH	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	6	FAIR	0
HOOD	6	FAIR	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	6	FAIR	0
LH FENDER	6	FULL DENT PAINTED	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
BODY RUST	6	FAIR	0
ROOF (REGULAR)	6	FAIR	0
PAINT CONDITION	6	BED	0
LH FRONT DOOR	5	DENT PAINTED	0
LH REAR DOOR	5	DENT PAINTED	0
LH RUNNING BOARD	5	DENT PAINTED	0
LH QUARTER PANEL	5	FULL DENT PAINTED	0
REAR BUMPER	5	REPAIR ,PAINTED	0

Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score **6/10**



4,07,696

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	5	DENT ,PAINTED	0
RH RUNNING BOARD	5	DENT,PAINTED	0
RH REAR DOOR	5	DENT ,PAINTED	0
RH FRONT DOOR	5	DENT,PAINTED	0
RH FENDER	5	DENT,PAINTED	0

IMAGES



NEED ATTENTION ⚠️



Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score



6/10



4,07,696

DOCUMENTS



DESCRIPTION

1 car condition very bed 2accendiatial car 3 noise engine 4 full body dent painted

Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score



6/10



4,07,696

IMAGES



Ordered by: Manik | Inspected date: 2018-08-27

Order Id: 22293

Overall Score



6/10



4,07,696

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.