

ECO INSPECTION REPORT Premium

Order ID : 23825

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Madhur	Inspection Date : 2018-09-17	Valid Till : 2018-12-17
------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 100 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**

377+ vehicle inspected










1+ years experience

Santosh Kumar

Toyota Innova 2.5 V 7 Str, 2012



VEHICLE INFORMATION			
MAKE	TOYOTA	TRANSMISSION TYPE	MANUAL
MODEL	INNOVA	REGISTRATION NO.	UP16AH8906
YEAR	2012	VIN/CHASIS NUMBER	308260
TRIM	2.5 V 7 STR	KMS RUN	108525
COLOR	SILVER	INSURANCE EXPIRY	2019-1-27
BODY TYPE	SUV	LOCATION	NOIDA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	40,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

6,65,273




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 3,500



Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score **6/10**



6,65,273

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	6	GOOD	0
NAVIGATION (NO)	0	NO	0

IMAGES



Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score



6/10



6,65,273



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	0	NO	0
REAR PARKING SENSORS (NO)	0		0
REAR VIEW CAMERA (NO)	0		0



IMAGES



WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY	7	GOOD	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score  **6/10**



6,65,273

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TAIL LIGHT	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	5	PAINTED	0
HOOD	5	PAINTED AND MINOR SCRATCH	3000
SIDE VIEW MIRRORS	5	PAINTED AND MINOR SCRATCH	500
LH FENDER	5	PAINTED	0
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED AND MINOR DENT	0
LH RUNNING BOARD	5	PAINTED	0
LH QUARTER PANEL	5	PAINTED	0
FUEL LID	5	PAINTED	0
REAR BUMPER	5	PAINTED	0
TRUNK LID/TAIL GATE	5	PAINTED	0
RH QUARTER PANEL	5	PAINTED	0

www.droom.in/eco

support@eco.com

Contact No. 1860 500 4444 (Toll Free)

-a service by  **droom**.in

Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score **6/10**



6,65,273

EXTERIOR (CONTINUED)


5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH RUNNING BOARD	5	PAINTED	0
RH REAR DOOR	5	PAINTED	0
RH FRONT DOOR	5	PAINTED	0
RH FENDER	5	PAINTED	0
PAINT CONDITION	5	ALL CAR IS PAINTED WITHOUT ROOF	0

IMAGES





NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

all car is painted without roof rear camera available car is better condition right side rear mi

www.droom.in/eco

support@eco.com

Contact No. 1860 500 4444 (Toll Free)

-a service by  **droom**.in

Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score




6/10



6,65,273

IMAGES





Ordered by: Madhur | Inspected date: 2018-09-17

Order Id: 23825

Overall Score



6/10



6,65,273

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

www.droom.in/eco

support@eco.com

Contact No. 1860 500 4444 (Toll Free)

-a service by  **droom**.in