

# ECO INSPECTION REPORT

Premium

Order ID : 24627

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Aparna	Inspection Date : 2018-09-26	Valid Till : 2018-12-27
------------------------	---------------------------------	----------------------------

## 6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

Inspected By

**Sourav Biswas**

✓ **Verified Technician**  
81+ vehicle inspected  
1+ years experience

## Maruti Suzuki Eeco 7 Str, 2013



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	EECO	REGISTRATION NO.	WB06H8753
YEAR	2013	VIN/CHASIS NUMBER	MA3ERLF1S00229880
TRIM	7 STR	KMS RUN	35018
COLOR	WHITE	INSURANCE EXPIRY	2019-3-1
BODY TYPE	SEDAN	LOCATION	KALINDI
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	2	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 2,05,534

## ECO SCORE & REPAIR COST ESTIMATE

### ECO SCORE

Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10

### TOTAL ESTIMATE SPEND 62,500

Category	Estimate Spend
Interior	0
Wheel	2,500
Test Drive	0
Exterior	40,000
Hood	20,000

Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534



## INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	7		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	6	OK	0
HORN	6	AVERAGE	0
SPEAKERS & MUSIC SYSTEM	6	OK	0
HANDBRAKE	6	AVERAGE	0
STEERING-MOUNTED CONTROLS	6	OK	0
PEDALS	6	OK	0
CENTRAL LOCK	6	NOT AVAILABLE	0
A/C VENTS & HEATER	6	NOT AVAILABLE	0
CUP HOLDERS	6	OK	0
NAVIGATION (NO)	6	NOT AVAILABLE	0
ODOMETER	6	OK	0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	6	OK	0



## IMAGES



Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534



NEED ATTENTION



TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE	0
BRAKE PERFORMANCE	6	OK	0
CLUTCH PERFORMANCE	6	OK	0
ENGINE NOISE	6	OK	0
IGNITION SYSTEM	6	NOT AVAILABLE	0
SUSPENSION PERFORMANCE	6	NOT AVAILABLE	0
SUSPENSION FRONT SHOCKS	6	OK	0
SUSPENSION REAR SHOCKS	6	OK	0
TRANSMISSION ENGAGE	6	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534

## WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
WHEEL ASSEMBLY	6	AVERAGE	0
SPARE TYRE (YES)	5	REQUIRED	2500

## IMAGES



## NEED ATTENTION ⚠



## HOOD



6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE	0
RH APRON	6	AVERAGE	0
RADIATOR	6	AVERAGE	0
BATTERY	6	OK	0
BRAKE FLUID LEVEL	6	OK	0
ENGINE OIL	6	OK	0

COOLANT LEVEL	6	OK	0
BRAKE & COOLANT HOSE PIPES	6	OK	0
UNDERCARRIAGE	7	OK	0
EXHAUST SYSTEM	6	OK	0
WIRING	5	REQUIRED	20000

## IMAGES



## NEED ATTENTION



Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	AVERAGE	0
FRONT BUMPER	6	OK	0
HEAD LIGHTS	6	OK	0
GRILLE	6	OK	0
TURN SIGNAL	6	OK	0
FOG LAMPS	6	OK	0
HOOD	6	AVERAGE	0
PILLAR	6	AVERAGE	0
FRONT WINDSHIELD	6	OK	0
SIDE VIEW MIRRORS	6	OK	0
LH FENDER	6	AVERAGE	0
LH FRONT DOOR	6	OK	0
LH REAR DOOR	6	OK	0
LH RUNNING BOARD	6	OK	0
LH QUARTER PANEL	6	OK	0
FUEL LID	6	AVERAGE	0
REAR WINDSHIELD	6	OK	0
REAR BUMPER	6	OK	0
TAIL LIGHT	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
LUGGAGE COMPARTMENT LIGHT	6	OK	0
RH QUARTER PANEL	6	OK	0
RH RUNNING BOARD	6	OK	0
RH REAR DOOR	6	OK	0

Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	OK	0
RH FENDER	7	OK	0
BODY RUST	6	OK	0
ROOF (REGULAR)	6	OK	0
<b>PAINT CONDITION</b>	<b>5</b>	<b>REQUIRED</b>	<b>40000</b>

IMAGES



NEED ATTENTION ⚠





Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score





6/10



2,05,534



DOCUMENTS



DESCRIPTION

Average

Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score





6/10



2,05,534

IMAGES





Ordered by: Aparna | Inspected date: 2018-09-26

Order Id: 24627

Overall Score



6/10



2,05,534

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.