

ECO INSPECTION REPORT

Premium

Order ID : 24885

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : MINTU	Inspection Date : 2018-09-29	Valid Till : 2018-12-29
-----------------------	---------------------------------	----------------------------

6/10

Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 114 does not need attention
- 1 Owner , 6 Years Vehicle Age
- No Accidental History

Inspected By

Verified Technician

93+ vehicle inspected

1+ years experience

Sourav Biswas

Tata Indigo Ecs Lx, 2012



VEHICLE INFORMATION			
MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	INDIGO ECS	REGISTRATION NO.	WB04F3189
YEAR	2012	VIN/CHASIS NUMBER	18053
TRIM	LX	KMS RUN	128399
COLOR	WHITE	INSURANCE EXPIRY	2019-8-16
BODY TYPE	SEDAN	LOCATION	PARKCIRCUS
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	2	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:

2,01,094

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior		6 / 10
Wheel		6 / 10
Test Drive		7 / 10
Exterior		6 / 10
Hood		6 / 10

TOTAL ESTIMATE SPEND 55,000

Category	Estimate Spend
Interior	0
Wheel	2,500
Test Drive	0
Exterior	27,500
Hood	25,000

Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score  **6/10**



2,01,094

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	6	OK	0
CARPET & FLOOR MAT	6	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	6	OK	0
HORN	6	OK	0
SPEAKERS & MUSIC SYSTEM	6	OK	0
HANDBRAKE	6	OK	0
STEERING-MOUNTED CONTROLS	7	OK	0
PEDALS	7	OK	0
CENTRAL LOCK	6	OK	0
A/C VENTS & HEATER	7	OK	0
CUP HOLDERS	7	AVERAGE	0
NAVIGATION (NO)	6	NOT AVAILABLE	0
ODOMETER	6	OK	0
POWER WINDOWS (YES)	6	OK	0
HAZARD LIGHT	6	OK	0

IMAGES



Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score



6/10



2,01,094



NEED ATTENTION



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	OK	0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score



6/10



2,01,094

WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	OK	0
WHEEL ASSEMBLY	6	OK	0
SPARE TYRE (YES)	5	NEED TO CHANGE	2500

IMAGES



NEED ATTENTION ⚠



HOOD



6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE	0
RH APRON	6	AVERAGE	0
RADIATOR	6	OK	0
BATTERY	6	OK	0
BRAKE FLUID LEVEL	6	OK	0
ENGINE OIL	6	OK	0

COOLANT LEVEL	6	OK	0
BRAKE & COOLANT HOSE PIPES	7	OK	0
UNDERCARRIAGE	6	OK	0
EXHAUST SYSTEM	6	OK	0
WIRING	5	REQUIRED	25000

IMAGES



NEED ATTENTION



Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score  **6/10**



2,01,094

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	6	OK	0
HEAD LIGHTS	6	OK	0
GRILLE	6	OK	0
TURN SIGNAL	6	OK	0
FOG LAMPS	6	OK	0
PILLAR	6	OK	0
FRONT WINDSHIELD	6	OK	0
SIDE VIEW MIRRORS	6	OK	0
LH FRONT DOOR	6	OK	0
LH REAR DOOR	6	OK	0
LH RUNNING BOARD	6	OK	0
FUEL LID	6	OK	0
REAR WINDSHIELD	6	OK	0
REAR BUMPER	6	OK	0
TAIL LIGHT	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
LUGGAGE COMPARTMENT LIGHT	6	OK	0
RH QUARTER PANEL	6	OK	0
RH RUNNING BOARD	6	OK	0
RH REAR DOOR	6	OK	0
RH FRONT DOOR	6	OK	0
RH FENDER	6	OK	0
BODY RUST	6	OK	0
ROOF (REGULAR)	6	OK	0

Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score **6/10**



2,01,094

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	5	CHANGES	500
HOOD	5	NEED TO CHANGE	1000
LH FENDER	5	DENT	500
LH QUARTER PANEL	5	DENT	500
PAINT CONDITION	5	REQUIRED	25000

IMAGES



NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

Average

Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score



6/10



2,01,094

IMAGES





Ordered by: MINTU | Inspected date: 2018-09-29

Order Id: 24885

Overall Score



6/10



2,01,094

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.