

ECO INSPECTION CERTIFICATE

Premium

Order ID : 24943

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Expat Direction Consultancy Services	Inspection Date : 2018-10-01	Valid Till : 2019-01-08
---	--	-----------------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **112** does not need attention
- ✔ **1** Owner , **5** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**










76+ vehicle inspected
1+ years experience

Gagan Gurawaliya

Toyota Innova 2.5 Gx 7 Str Bs Iv, 2013



VEHICLE INFORMATION			
MAKE	TOYOTA	TRANSMISSION TYPE	MANUAL
MODEL	INNOVA	REGISTRATION NO.	HR55T2604
YEAR	2013	VIN/CHASIS NUMBER	439240
TRIM	2.5 GX 7 STR BS IV	KMS RUN	0000
COLOR	WHITE	INSURANCE EXPIRY	2017-12-30
BODY TYPE	SUV	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (ONE MONTH)
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	YES (DUPLICATE)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



orangebookvalue.com






Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

8,21,130




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		
 Interior	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10
 Wheel	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10
 Test Drive	<div style="width: 70%; height: 10px; background: linear-gradient(to right, green, gray);"></div>	7 / 10
 Exterior	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10
 Hood	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, gray);"></div>	6 / 10

TOTAL ESTIMATE SPEND 31,000



Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score  **6/10**



8,21,130

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (NO)	0	NA	0

IMAGES



Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score **6/10**



8,21,130

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY	6	GOOD	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0

 IMAGES



Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score  **6/10**



8,21,130

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
LH FENDER	6	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH REAR DOOR	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0
RH FRONT DOOR	6	GOOD	0
RH FENDER	6	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	6	GOOD	0
FOG LAMPS	0	NA	0
SIDE VIEW MIRRORS	5	NEED TO REPAIR	5000

Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score **6/10**



8,21,130

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH RUNNING BOARD	5	NEED TO REPAIR	5000
LH QUARTER PANEL	5	NEED TO REPAIR	5000
REAR BUMPER	5	NEED TO REPAIR	6000
TAIL LIGHT	5	NEED TO REPAIR	5000
RH QUARTER PANEL	5	NEED TO REPAIR	5000

IMAGES



NEED ATTENTION



Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score




6/10



8,21,130

 DOCUMENTS



 DESCRIPTION

minor scratches battery need to replace rear bumper is already repaired

Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score




6/10



8,21,130

IMAGES



Ordered by: Expat Direction Consultancy Services | Inspected date: 2018-10-01

Order Id: 24943

Overall Score



6/10



8,21,130

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.