

ECO INSPECTION REPORT

Premium

Order ID : 24987

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Anil | Inspection Date : 2018-09-28 | Valid Till : 2018-12-28

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By









✓ Verified Technician
 42+ vehicle inspected
 1+ years experience

Gagan Gurawaliya

Mahindra Quanto C6, 2012



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	QUANTO	REGISTRATION NO.	HR26BV3225
YEAR	2012	VIN/CHASIS NUMBER	44700
TRIM	C6	KMS RUN	93573
COLOR	OTHER	INSURANCE EXPIRY	2018-10-18
BODY TYPE	SUV	LOCATION	SEC 23 GURGAON
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (ONE MONTH)
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO

 Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.











With this evaluation, the Fair Market Price for this vehicle comes to be:

2,72,859


 Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior		7 / 10
 Wheel		7 / 10
 Test Drive		8 / 10
 Exterior		6 / 10
 Hood		7 / 10

TOTAL ESTIMATE SPEND 39,400



Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score **7/10**



2,72,859

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	6	NA	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

IMAGES



Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score **7/10**



2,72,859

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score  **7/10**



2,72,859

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FRONT BUMPER	5	NEED TO BE REPAIR	4000
SIDE VIEW MIRRORS	5	NEED TO BE REPAIR	3000
LH FENDER	5	NEED TO BE REPAIR	4000
LH FRONT DOOR	5	NEED TO REPAIR	5000
LH REAR DOOR	5	NEED TO REPAIR	5000

Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score



7/10



2,72,859



EXTERIOR (CONTINUED)



6/10





INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH QUARTER PANEL	5	NEED TO REPAIR	400
REAR BUMPER	5	NEED TO REPAIR	4000
RH QUARTER PANEL	5	NEED TO REPAIR	4000
RH REAR DOOR	5	NEED TO REPAIR	5000
RH FRONT DOOR	5	NEED TO REPAIR	5000



IMAGES




NEED ATTENTION





DOCUMENTS



DESCRIPTION

minor scratches spare wheel also need to replace after 5000 km both rear tyres need to be replaced a

Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score




7/10



2,72,859

IMAGES





Ordered by: Anil | Inspected date: 2018-09-28

Order Id: 24987

Overall Score



7/10



2,72,859

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.