


ECO INSPECTION CERTIFICATE

Premium

Order ID : 27468

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Abhishek	Inspection Date : 2018-10-16	Valid Till : 2019-01-18	Inspected By  Abu Zafar
--------------------------	---------------------------------	----------------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
33+ vehicle inspected
1+ years experience

Hyundai Verna 1.6 Vtvt Sx (O) At, 2013



VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	AUTOMATIC
MODEL	VERNA	REGISTRATION NO.	DL8CP3737
YEAR	2013	VIN/CHASIS NUMBER	110680
TRIM	1.6 VTVT SX (O) AT	KMS RUN	32470
COLOR	SILVER	INSURANCE EXPIRY	2019-2-16
BODY TYPE	SEDAN	LOCATION	SHAHDRRA
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)		RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,74,186




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10
Hygiene & Cleanliness	<div style="width: 50%;"></div>	5 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score



7/10



5,74,186



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
CUP HOLDERS	8	GOOD	0
ODOMETER	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



IMAGES



Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score **7/10**




5,74,186

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	8	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score  **7/10**



5,74,186

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	8	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOF	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0

Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score **7/10**




5,74,186

EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	NA	0
PAINT CONDITION	9	GOOD	0

IMAGES



DOCUMENTS



DESCRIPTION

all condition is good but some scratches like as both bumper left side quarter panel

Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score












7/10



5,74,186

IMAGES



Ordered by: Abhishek | Inspected date: 2018-10-16

Order Id: 27468

Overall Score



7/10



5,74,186

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.