

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 28276

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Manjit	Inspection Date : 2018-10-23	Valid Till : 2019-01-23	Inspected By  <b>Praveen Singh</b> <span style="color: green;">✓</span> <b>Verified Technician</b> 91+ vehicle inspected 1+ years experience
<h2>6/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> <li><span style="color: green;">✓</span> Evaluated across <b>5</b> segments</li> <li><span style="color: green;">✓</span> Covered <b>121+</b> checkpoints</li> <li><span style="color: green;">✓</span> <b>119</b> does not need attention</li> <li><span style="color: green;">✓</span> <b>1</b> Owner , <b>6</b> Years Vehicle Age</li> <li><span style="color: green;">✓</span> No Accidental History</li> </ul>	

## Skoda Superb ELEGANCE 1.8 TSI AT, 2012



### VEHICLE INFORMATION

MAKE	SKODA	TRANSMISSION TYPE	AUTOMATIC
MODEL	SUPERB	REGISTRATION NO.	MH02CP7004
YEAR	2012	VIN/CHASIS NUMBER	TMBBBC3T2CA300437
TRIM	ELEGANCE 1.8 TSI AT	KMS RUN	99002
COLOR	OTHER	INSURANCE EXPIRY	2018-10-11
BODY TYPE	SEDAN	LOCATION	ANDHERI
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (DUPLICATE)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**9,15,519**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 4,000



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score



6/10



9,15,519



## INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	6	NO DAMAGE	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	NO DAMAGE	0
HORN	7	NO DAMAGE	0
SPEAKERS & MUSIC SYSTEM	7	GOOD SYSTEM	0
HANDBRAKE	7	NO DAMAGE	0
STEERING-MOUNTED CONTROLS	7	NO DAMAGE	0
PEDALS	7	NO DAMAGE	0
CENTRAL LOCK	7	NO DAMAGE	0
A/C VENTS & HEATER	7	GOOD COOLING	0
CUP HOLDERS	7	NO DAMAGE	0
ODOMETER	6	GOOD	0
HAZARD LIGHT	7	NO DAMAGE	0



## IMAGES



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score



6/10



9,15,519



NEED ATTENTION



TEST DRIVE




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	NO DAMAGE	0
BRAKE PERFORMANCE	7	NO DAMAGE	0
CLUTCH PERFORMANCE	6	NO DAMAGE	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	NO DAMAGE	0
SUSPENSION PERFORMANCE	6	NO DAMAGE	0
SUSPENSION FRONT SHOCKS	6	NO DAMAGE	0
SUSPENSION REAR SHOCKS	6	NO DAMAGE	0
TRANSMISSION ENGAGE	6	NO DAMAGE	0



IMAGES



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score **6/10**



**9,15,519**

## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD TREAD	0

## IMAGES



## NEED ATTENTION




## HOOD

**6/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NO DAMAGE	0
RH APRON	6	NO DAMAGE	0
RADIATOR	6	NO DAMAGE	0
WIRING	6	NO DAMAGE	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAX LEVEL	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	7	MAX LEVEL	0

BRAKE & COOLANT HOSE PIPES	6	NO DAMAGE	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	NO DAMAGE	0

## IMAGES



## NEED ATTENTION



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score



6/10



9,15,519

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	NO DAMAGE	0
HEAD LIGHTS	7	NO DAMAGE	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	6	NO DAMAGE	0
FOG LAMPS	6	NO DAMAGE	0
HOOD	6	NO DAMAGE	0
PILLAR	6	NO DAMAGE	0
FRONT WINDSHIELD	7	NO DAMAGE	0
SIDE VIEW MIRRORS	6	NO DAMAGE	0
LH FENDER	6	NO DAMAGE	0
LH FRONT DOOR	6	NO DAMAGE	0
LH REAR DOOR	6	NO DAMAGE	0
LH RUNNING BOARD	6	NO DAMAGE	0
LH QUARTER PANEL	6	NO DAMAGE	0
FUEL LID	6	NO DAMAGE	0
REAR WINDSHIELD	7	NO DAMAGE	0
TAIL LIGHT	7	NO DAMAGE	0
TRUNK LID/TAIL GATE	6	NO DAMAGE	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD SPACE	0
RH QUARTER PANEL	6	NO DAMAGE	0
RH RUNNING BOARD	6	NO DAMAGE	0
RH REAR DOOR	6	NO DAMAGE	0
RH FRONT DOOR	6	NO DAMAGE	0
RH FENDER	6	NO DAMAGE	0



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score  **6/10**



**9,15,519**

**EXTERIOR (CONTINUED)**

**6/10**




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6	NO RUSH	0
PAINT CONDITION	6	GOOD PAINT	0
FRONT BUMPER	5	PAINTING	2000
REAR BUMPER	5	PAINTING	2000

**IMAGES**




**NEED ATTENTION** ⚠️





## DOCUMENTS



## DESCRIPTION

good car well maintain car with good interior



Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score




6/10








9,15,519

 IMAGES







Ordered by: Manjit | Inspected date: 2018-10-23

Order Id: 28276

Overall Score



6/10



9,15,519

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.