

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 28397

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sweety	Inspection Date : 2018-10-22	Valid Till : 2019-01-22
------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 109 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By

Verified Technician

19+ vehicle inspected  
1+ years experience

Aabid Ali

## Hyundai I10 MAGNA 1.2, 2012



### VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	I10	REGISTRATION NO.	DL8CAA2602
YEAR	2012	VIN/CHASIS NUMBER	043410
TRIM	MAGNA 1.2	KMS RUN	105387
COLOR	GREY	INSURANCE EXPIRY	2013-7-12
BODY TYPE	HATCHBACK	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (ONE MONTH)
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,24,198




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 35,600



Ordered by: sweety | Inspected date: 2018-10-22

Order Id: 28397

Overall Score



6/10



2,24,198



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
ODOMETER	7	GOOD	0
HAZARD LIGHT	7	GOOD	0



## IMAGES



Ordered by: sweety | Inspected date: 2018-10-22

Order Id: 28397

Overall Score  **6/10**



**2,24,198**

**NEED ATTENTION** ⚠️



**TEST DRIVE**

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0

**IMAGES**



Ordered by: **sweety** | Inspected date: 2018-10-22

Order Id: 28397

Overall Score **6/10**




**2,24,198**

## WHEEL

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0

## IMAGES



## NEED ATTENTION




## HOOD

**7/10**



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0

BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

## IMAGES



## NEED ATTENTION



Ordered by: sweety | Inspected date: 2018-10-22

Order Id: 28397

Overall Score



6/10



2,24,198

 EXTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	6	MINOR DAMZE	5000
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	6	SCRATCH	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	6	DAMAZE	4000
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	SCRATCH	1500
RH RUNNING BOARD	6	GOOD	0
RH FRONT DOOR	6	SCRATCH	1500
PAINT CONDITION	6	GOOD	0
LICENSE PLATE	4	DAMAZE	600
FRONT BUMPER	5	SCRATCH AND BROKEN	4000
HEAD LIGHTS	5	SCRATCH	3500
GRILLE	4	BROKEN	1500
FOG LAMPS	1	NA	2000
LH FRONT DOOR	5	SCRATCH	1500
LH REAR DOOR	5	SCRATCH	1500
LH RUNNING BOARD	5	MINOR DANT	2000



Ordered by: sweety | Inspected date: 2018-10-22

Order Id: 28397

Overall Score



6/10



2,24,198



## EXTERIOR (CONTINUED)




5/10







INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH QUARTER PANEL	4	SCRATCH	1500
RH REAR DOOR	5	SCRATCH AND DANT	3000
RH FENDER	5	SCRATCH	1500
BODY RUST	5	SOME PART RUSTED	1000




## IMAGES




## NEED ATTENTION





## 🚗 DOCUMENTS



## 🚗 DESCRIPTION

all body scratches rear and front bumper broken minor damage windscreen all body minor dant steel



Ordered by: **sweety** | Inspected date: 2018-10-22

Order Id: 28397

Overall Score




**6/10**












**2,24,198**

**IMAGES**







Ordered by: **sweety** | Inspected date: 2018-10-22

Order Id: 28397

Overall Score



6/10



2,24,198

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.