

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 28493

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sam	Inspection Date : 2018-10-23	Valid Till : 2019-01-23
---------------------	---------------------------------	----------------------------

## 7/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **2** Owners , **6** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ **Verified Technician**

169+ vehicle inspected  
1+ years experience

Sourav Biswas

## Mahindra Xuv500 W8, 2012



### VEHICLE INFORMATION

MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	XUV500	REGISTRATION NO.	WB02AA3615
YEAR	2012	VIN/CHASIS NUMBER	NA
TRIM	W8	KMS RUN	31166
COLOR	BLACK	INSURANCE EXPIRY	2018-10-23
BODY TYPE	SEDAN	LOCATION	KHIDIRPUR
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLENO		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

**6,09,559**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10
Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score



7/10



6,09,559



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	OK	0
DOOR HINGES	7	OK	0
CARPET & FLOOR MAT	7	OK	0
SEAT & SEAT BELT	7	OK	0
DASHBOARD & INSTRUMENT PANEL	8	OK	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	7	OK	0
HANDBRAKE	7	OK	0
STEERING-MOUNTED CONTROLS	7	OK	0
PEDALS	7	OK	0
CENTRAL LOCK	7	OK	0
A/C VENTS & HEATER	7	OK	0
CUP HOLDERS	6	AVAILABLE	0
ODOMETER	6	OK	0
HAZARD LIGHT	7	OK	0



## IMAGES



Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score



7/10



6,09,559



NEED ATTENTION



TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	OK	0
BRAKE PERFORMANCE	7	OK	0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	7		0
IGNITION SYSTEM	6	OK	0
SUSPENSION PERFORMANCE	7	OK	0
SUSPENSION FRONT SHOCKS	7	OK	0
SUSPENSION REAR SHOCKS	7	OK	0
TRANSMISSION ENGAGE	7	OK	0



IMAGES



Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score  **7/10**



**6,09,559**

## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	OK	0

## IMAGES



## NEED ATTENTION



## HOOD

**7/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	OK	0
RH APRON	6	OK	0
RADIATOR	7	OK	0
WIRING	6	OK	0
BATTERY	7	OK	0
BRAKE FLUID LEVEL	6	OK	0
ENGINE OIL	7	OK	0
COOLANT LEVEL	7	OK	0

BRAKE & COOLANT HOSE PIPES	7	OK	0
UNDERCARRIAGE	6	OK	0
EXHAUST SYSTEM	7	OK	0

## IMAGES



## NEED ATTENTION



Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score  **7/10**



**6,09,559**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	AVERAGE	0
FRONT BUMPER	7	OK	0
HEAD LIGHTS	6	OK	0
GRILLE	7	OK	0
TURN SIGNAL	7	OK	0
FOG LAMPS	7	OK	0
HOOD	7	OK	0
PILLAR	7	OK	0
FRONT WINDSHIELD	7	OK	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	7	OK	0
LH FRONT DOOR	7	OK	0
LH REAR DOOR	7	OK	0
LH RUNNING BOARD	7	OK	0
LH QUARTER PANEL	7	OK	0
FUEL LID	7	OK	0
REAR WINDSHIELD	7	OK	0
REAR BUMPER	7	OK	0
TAIL LIGHT	7	OK	0
TRUNK LID/TAIL GATE	7	OK	0
LUGGAGE COMPARTMENT LIGHT	7	OK	0
RH QUARTER PANEL	7	OK	0
RH RUNNING BOARD	7	OK	0
RH REAR DOOR	7	OK	0

Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score



7/10



6,09,559



## EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	OK	0
RH FENDER	7	OK	0
BODY RUST	8	OK	0
PAINT CONDITION	7	OK	0




## IMAGES



## NEED ATTENTION





## DESCRIPTION

good condition



Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score







7/10



6,09,559

IMAGES





Ordered by: sam | Inspected date: 2018-10-23

Order Id: 28493

Overall Score



7/10



6,09,559

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.