

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 29039

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Shishir	Inspection Date : 2018-10-27	Valid Till : 2019-01-28
-------------------------	---------------------------------	----------------------------

## 7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **118** does not need attention
- ✔ **1** Owner , **5** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

97+ vehicle inspected  
1+ years experience

Arjun Kumar









## Audi A6 2.0 TDI, 2013



### VEHICLE INFORMATION

MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A6	REGISTRATION NO.	UP16AQ6013
YEAR	2013	VIN/CHASIS NUMBER	02815
TRIM	2.0 TDI	KMS RUN	40604
COLOR	WHITE	INSURANCE EXPIRY	2018-10-31
BODY TYPE	OTHER	LOCATION	NOIDA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (FULL)
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**24,60,209**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 1,10,000



Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score



7/10



24,60,209



## INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
CUP HOLDERS	8	GOOD	0
ODOMETER	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



## IMAGES



Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score  **7/10**





**24,60,209**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	6	NO SPACE TO DRIVE SO NOT CHECK NEED ROAD TEST THEN GIVE REPORT	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0
ENGINE NOISE	4	V-BELT SIDE NOISY NEED CHECK THEN GIVE REPORT	5000

## IMAGES



## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0

 IMAGES




 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	8	GOOD	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0
ENGINE OIL	1	NEED REPLACE SERVICE DUE	40000

 IMAGES





Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score  **7/10**



**24,60,209**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	6	MINOR SCRATCHES	0
HEAD LIGHTS	8	GOOD	0
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	6	SCRATCHES	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	6	MINOR SCRATCHES	0
LH QUARTER PANEL	6	MINOR SCRATCHES AND DENT	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	6	MINOR SCRATCHES	0
TAIL LIGHT	8	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	6	MINOR DENT	0
RH RUNNING BOARD	6	MINOR SCRATCHES	0
RH REAR DOOR	8	GOOD	0
RH FRONT DOOR	8	GOOD	0



Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score  **7/10**




**24,60,209**


## EXTERIOR (CONTINUED)

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	MINOR PAINT REMOVED	0
BODY RUST	8	GOOD	0
PAINT CONDITION	6	NEED TO TOUCHING	30000
FRONT WINDSHIELD	4	STONE CHIP MARK	35000




## IMAGES





 DOCUMENTS





## DESCRIPTION

front and rear bumper having scratches body having minor Dent and scratches need touching front tyre

Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score




7/10





24,60,209

IMAGES











Ordered by: Shishir | Inspected date: 2018-10-27

Order Id: 29039

Overall Score



7/10



24,60,209

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.