

ECO INSPECTION CERTIFICATE

Premium


Order ID : 30159

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gurvin	Inspection Date : 2018-11-10	Valid Till : 2019-02-10	Inspected By Manoj Kumar ✔ Verified Technician 146+ vehicle inspected 1+ years experience
<h2>8/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> ✔ Evaluated across 5 segments ✔ Covered 121+ checkpoints ✔ 121 does not need attention ✔ 1 Owner , 0 Years Vehicle Age ✔ No Accidental History 	

Jaguar F-Pace PRESTIGE, 2018



VEHICLE INFORMATION			
MAKE	JAGUAR	TRANSMISSION TYPE	AUTOMATIC
MODEL	F-PACE	REGISTRATION NO.	HR26 BW0000
YEAR	2018	VIN/CHASIS NUMBER	992257
TRIM	PRESTIGE	KMS RUN	15235
COLOR	RED	INSURANCE EXPIRY	2019-2-12
BODY TYPE	SUV	LOCATION	DLF PHASE 5
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	NO
		SERVICE LOGS AVAILABLE	YES (FULL)
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

66,50,139

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 0	
Interior	<div style="width: 90%; background-color: green;"></div> 9 / 10	Interior	0
Wheel	<div style="width: 80%; background-color: green;"></div> 8 / 10	Wheel	0
Test Drive	<div style="width: 90%; background-color: green;"></div> 9 / 10	Test Drive	0
Exterior	<div style="width: 90%; background-color: green;"></div> 9 / 10	Exterior	0
Hood	<div style="width: 90%; background-color: green;"></div> 9 / 10	Hood	0

Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score



8/10



66,50,139



INTERIOR




9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9	GOOD	0
DOOR HINGES	9	GOOD	0
CARPET & FLOOR MAT	9	GOOD	0
SEAT & SEAT BELT	9	GOOD	0
DASHBOARD & INSTRUMENT PANEL	9	GOOD	0
HORN	9	GOOD	0
SPEAKERS & MUSIC SYSTEM	9	GOOD	0
HANDBRAKE	9	GOOD	0
STEERING-MOUNTED CONTROLS	9	GOOD	0
PEDALS	9	GOOD	0
CENTRAL LOCK	9	GOOD	0
A/C VENTS & HEATER	9	GOOD	0
CUP HOLDERS	9	GOOD	0
ODOMETER	9	GOOD	0
HAZARD LIGHT	9	GOOD	0



IMAGES



Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score **8/10**




66,50,139

TEST DRIVE

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9	GOOD	0
BRAKE PERFORMANCE	9	GOOD	0
CLUTCH PERFORMANCE	9	GOOD	0
ENGINE NOISE	9	GOOD	0
IGNITION SYSTEM	9	GOOD	0
SUSPENSION PERFORMANCE	9	GOOD	0
SUSPENSION FRONT SHOCKS	9	GOOD	0
SUSPENSION REAR SHOCKS	9	GOOD	0
TRANSMISSION ENGAGE	9	GOOD	0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0

 IMAGES




 HOOD



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	9	GOOD	0
RH APRON	9	GOOD	0
RADIATOR	9	GOOD	0
WIRING	9	GOOD	0
BATTERY	9	GOOD	0
BRAKE FLUID LEVEL	9	GOOD	0
ENGINE OIL	9	GOOD	0
COOLANT LEVEL	9	GOOD	0
BRAKE & COOLANT HOSE PIPES	9	GOOD	0
UNDERCARRIAGE	9	GOOD	0
EXHAUST SYSTEM	9	GOOD	0

 IMAGES



Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score



8/10



66,50,139

 EXTERIOR



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9	GOOD	0
FRONT BUMPER	9	GOOD	0
HEAD LIGHTS	9	GOOD	0
GRILLE	9	GOOD	0
TURN SIGNAL	9	GOOD	0
FOG LAMPS	9	GOOD	0
HOOD	9	GOOD	0
PILLAR	9	GOOD	0
FRONT WINDSHIELD	9	GOOD	0
SIDE VIEW MIRRORS	9	GOOD	0
LH FENDER	9	GOOD	0
LH FRONT DOOR	9	GOOD	0
LH REAR DOOR	9	GOOD	0
LH RUNNING BOARD	9	GOOD	0
LH QUARTER PANEL	9	GOOD	0
FUEL LID	9	GOOD	0
REAR WINDSHIELD	9	GOOD	0
REAR BUMPER	9	GOOD	0
TAIL LIGHT	9	GOOD	0
TRUNK LID/TAIL GATE	9	GOOD	0
LUGGAGE COMPARTMENT LIGHT	9	GOOD	0
RH QUARTER PANEL	9	GOOD	0
RH RUNNING BOARD	9	GOOD	0
RH REAR DOOR	9	GOOD	0

Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score



8/10



66,50,139



EXTERIOR (CONTINUED)







9/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	9	GOOD	0
RH FENDER	9	GOOD	0
BODY RUST	9	GOOD	0
PAINT CONDITION	9	GOOD	0



IMAGES



DOCUMENTS



DESCRIPTION

car in very good condition

Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score




8/10



66,50,139

IMAGES



Ordered by: gurvin | Inspected date: 2018-11-10

Order Id: 30159

Overall Score



8/10



66,50,139



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.