

ECO INSPECTION CERTIFICATE

Premium

Order ID : 31321

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Mohd	Inspection Date : 2018-11-19	Valid Till : 2019-02-19
----------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ Verified Technician

68+ vehicle inspected
1+ years experience

Abdul Qadeer

Tata Indica V2 LS, 2014



VEHICLE INFORMATION

MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	INDICA V2	REGISTRATION NO.	TS07UB1488
YEAR	2014	VIN/CHASIS NUMBER	MAT600185ETH10577
TRIM	LS	KMS RUN	157489
COLOR	SILVER	INSURANCE EXPIRY	2017-11-17
BODY TYPE	HATCHBACK	LOCATION	UPPARPALLY
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	19,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,82,688




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%; background-color: green;"></div>	8 / 10
 Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
 Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Hood	<div style="width: 80%; background-color: green;"></div>	8 / 10

TOTAL ESTIMATE SPEND 4,000



Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score



7/10



1,82,688



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	9	GOOD	0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	10	NOT AVAILABLE	0
PEDALS	9		0
CENTRAL LOCK	10	NOT AVAILABLE	0
A/C VENTS & HEATER	7		0
CUP HOLDERS	8		0
ODOMETER	8		0
HAZARD LIGHT	8		0



IMAGES



Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score **7/10**



1,82,688

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	7		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	9		0
RH APRON	9		0
RADIATOR	8		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score  **7/10**



1,82,688

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FADED	0
FRONT BUMPER	6		0
HEAD LIGHTS	7	LEFT DULL	0
GRILLE	8		0
TURN SIGNAL	7		0
FOG LAMPS	7	NOT AVAILABLE - LEFT COVER BROKEN	0
HOOD	6		0
PILLAR	7		0
SIDE VIEW MIRRORS	8		0
LH FENDER	6		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6		0
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	6		0
RH REAR DOOR	7		0
RH FRONT DOOR	6		0

Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score **7/10**



1,82,688


EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6		0
BODY RUST	8		0
PAINT CONDITION	7		0
FRONT WINDSHIELD	5	DAMAGED	4000

IMAGES





DOCUMENTS



DESCRIPTION

Vehicle needs attention. exterior attention. And too 1.5 l running is done

Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score










7/10



1,82,688

IMAGES





Ordered by: mohd | Inspected date: 2018-11-19

Order Id: 31321

Overall Score



7/10



1,82,688

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.