

ECO INSPECTION CERTIFICATE

Premium

Order ID : 31449

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Jiss

Inspection Date :
2018-11-23

Valid Till :
2019-02-23

5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 96 does not need attention
- ✓ 2 Owners , 9 Years Vehicle Age
- ✓ 1 Accidental History Reported

Inspected By



Santosh Kumar

- ✓ Verified Technician
- 585+ vehicle inspected
- 1+ years experience

Fiat Linea EMOTION 1.3, 2009



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	LINEA	REGISTRATION NO.	HR26AW5585
YEAR	2009	VIN/CHASIS NUMBER	000524
TRIM	EMOTION 1.3	KMS RUN	96157
COLOR	RED	INSURANCE EXPIRY	2018-9-19
BODY TYPE	SEDAN	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	YES	MAJOR ACCIDENT(S)	YES	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,23,671




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 40%;"></div>	4 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 50%;"></div>	5 / 10

TOTAL ESTIMATE SPEND 62,000



Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score



5/10



2,23,671



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0
CARPET & FLOOR MAT	5	NEED DRYCLINIG	2000



IMAGES



Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score **5/10**



2,23,671

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	6	GOOD	0
ENGINE NOISE	5	MINOR NOISE	0
SUSPENSION PERFORMANCE	4	MINOR SOUND	6000

IMAGES




WHEEL

4/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0
TYRES	3	BAD CONDITION	16000
SPARE TYRE (YES)	3	BAD CONDITION	4000

 IMAGES




 HOOD



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
ENGINE OIL	3	BAD	3000
COOLANT LEVEL	3	BAD	500
EXHAUST SYSTEM	5	MINOR BLACK SMOKE	5000

 IMAGES



Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score  **5/10**



2,23,671

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH FRONT DOOR	6	MINOR PAINTED	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	5	PAINTED AND SCRATCH	3000
FOG LAMPS	3	NOT WORKING	3500
HOOD	3	PAINTED AND ACCIDENT	0
SIDE VIEW MIRRORS	5	PAINTED AND SCRATCH	1000
LH FENDER	5	PAINTED AND MINOR SCRATCH	1000
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED AND SCRATCH	2500
LH RUNNING BOARD	5	PAINTED	0
LH QUARTER PANEL	5	PAINTED	0
REAR BUMPER	5	PAINTED AND SCRATCH	3000
TAIL LIGHT	4	AVERAGE CONDITION	3500
TRUNK LID/TAIL GATE	5	MINOR PAINTED AND SCRATCH	2500

Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score



5/10



2,23,671



EXTERIOR (CONTINUED)





5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	5	PAINTED	0
RH RUNNING BOARD	3	PAINTED AND DENT	3000
RH REAR DOOR	5	MINOR PAINTED AND SCRATCH	2500
RH FENDER	5	PAINTED	0
PAINT CONDITION	5	FULL CAR IS PAINTED WITHOUT ROOF	0





IMAGES





DOCUMENTS



DESCRIPTION

full car is painted without roof and dukey frant side accident tyres are bad suspension is bad

Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score





5/10



2,23,671

IMAGES





Ordered by: Jiss | Inspected date: 2018-11-23

Order Id: 31449

Overall Score



5/10



2,23,671



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.