



# ECO INSPECTION CERTIFICATE

Premium

Order ID : 31636

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Monika	Inspection Date : 2018-11-24	Valid Till : 2019-02-25	 Inspected By   Aabid Ali <span style="color: green;">✔</span> <b>Verified Technician</b> 75+ vehicle inspected 1+ years experience
------------------------	---------------------------------	----------------------------	---

**6/10**

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **111** does not need attention
- ✔ **1** Owner , **7** Years Vehicle Age
- ✔ No Accidental History

## Maruti Suzuki Alto LXI CNG, 2011



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	ALTO	REGISTRATION NO.	DL36BS1990
YEAR	2011	VIN/CHASIS NUMBER	830203LDDLL
TRIM	LXI CNG	KMS RUN	105158
COLOR	WHITE	INSURANCE EXPIRY	2017-11-9
BODY TYPE	HATCHBACK	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (PARTIAL)
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**1,37,439**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 50%;"></div>	5 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 34,500



Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score



6/10



1,37,439



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	6	GOOD	0



## IMAGES



Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score  **6/10**




**1,37,439**

## TEST DRIVE

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0

 IMAGES



Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score



6/10



1,37,439

 EXTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	SCRATCHES	2000
RH FRONT DOOR	7	GOOD	0
RH FENDER	6	DENT NEED TO REPAIR	3000
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	4	SCRATCHES NEED TO REPAIR	2000
HEAD LIGHTS	3	L.S NOT WORKING	1500
FOG LAMPS	0	NA	0
LH FENDER	3	DENT AND SCRATCHES	3000
LH FRONT DOOR	3	SCRATCHES	2000

Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score



6/10



1,37,439



## EXTERIOR (CONTINUED)




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH REAR DOOR	0	DENT AND SCRATCHES	5000
LH QUARTER PANEL	3	SCRATCHES	2000
REAR BUMPER	0	BROKEN NEED TO CHANGE	5000
TAIL LIGHT	0	BROKEN NEED TO CHANGE	2000
PAINT CONDITION	3	ALL BODY SCRATCHES NEED TO PAINT	7000



## IMAGES





## DOCUMENTS



## DESCRIPTION

all body dented need to repair tail light broken L.S. rear bumper need to change all body scratch

Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score




6/10



1,37,439

IMAGES







Ordered by: monika | Inspected date: 2018-11-24

Order Id: 31636

Overall Score



6/10



1,37,439

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.