

ECO INSPECTION CERTIFICATE

Premium

Order ID : 31697

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Manish	Inspection Date : 2018-11-23	Valid Till : 2019-02-23	Inspected By Verified Technician 2+ vehicle inspected 1+ years experience Yash Mishra
<h2>9/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> Evaluated across 5 segments Covered 121+ checkpoints 115 does not need attention 1 Owner , 6 Years Vehicle Age No Accidental History 	

Maruti Suzuki Swift VDI, 2012



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	SWIFT	REGISTRATION NO.	GJ01KQ9821
YEAR	2012	VIN/CHASIS NUMBER	MA3FHEB1SOO302426
TRIM	VDI	KMS RUN	161272
COLOR	RED	INSURANCE EXPIRY	2018-11-23
BODY TYPE	SEDAN	LOCATION	AHMEDABAD
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	60,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,38,171




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 100%;"></div>	10 / 10
Wheel	<div style="width: 100%;"></div>	10 / 10
Test Drive	<div style="width: 100%;"></div>	10 / 10
Exterior	<div style="width: 90%;"></div>	9 / 10
Hood	<div style="width: 100%;"></div>	10 / 10

TOTAL ESTIMATE SPEND 14,550



Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score



9/10



2,38,171



INTERIOR





10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	10	DO NOT EXIST	0
PEDALS	10		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION (NO)	10		0
ODOMETER	10		0
POWER WINDOWS (YES)	10		0
HAZARD LIGHT	10		0



IMAGES



Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score



9/10



2,38,171


TEST DRIVE



10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	10		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL



10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	10	BRAND NEW TIRES	0
SPARE TYRE (YES)	10		0
WHEEL ASSEMBLY (STEEL RIM)	10		0

 IMAGES




 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	10	NEW BATTERY DATE OF INSTALLATION 31/07/2018	0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES



Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score **9/10**



2,38,171

EXTERIOR

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	10		0
GRILLE	10		0
TURN SIGNAL	10		0
HOOD	7		0
PILLAR	10		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	10		0
LH FENDER	7		0
LH FRONT DOOR	7	NEEDS HAMMARY	500
LH REAR DOOR	7	NEEDS REPAIR AND PAINT	1500
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10	DOES NOT EXIST	0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0
FRONT BUMPER	3	BUMPER REPAIR AND PAINT REQUIRED	2500

Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score **9/10**



2,38,171

EXTERIOR (CONTINUED)

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	5	HEADLIGHT NEEDS TO BE REPLACED	5200
FOG LAMPS	5	NEEDS PROPER FITTING	100
REAR BUMPER	5	NEEDS REPAIR AND PAINT	1500
TAIL LIGHT	0	LH TAILLIGHT BROKEN	1750
RH REAR DOOR	5	NEEDS PAINT	1500

IMAGES



DOCUMENTS



DESCRIPTION

Overall the car is good with regards to driving ,but needs a bit of denting and painting work, to ma

Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score




9/10



2,38,171

IMAGES



Ordered by: manish | Inspected date: 2018-11-23

Order Id: 31697

Overall Score



9/10



2,38,171

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.