

ECO INSPECTION CERTIFICATE

Premium

Order ID : 32086

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Kshitij	Inspection Date : 2018-12-01	Valid Till : 2019-03-01
-------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **110** does not need attention
- ✔ **2** Owners , **6** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

613+ vehicle inspected

1+ years experience

Santosh Kumar

Audi A6 2.0 TDI Premium Plus, 2012



VEHICLE INFORMATION

MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A6	REGISTRATION NO.	UP78CS9999
YEAR	2012	VIN/CHASIS NUMBER	Y000933
TRIM	2.0 TDI PREMIUM PLUS	KMS RUN	63293
COLOR	WHITE	INSURANCE EXPIRY	2019-6-23
BODY TYPE	SEDAN	LOCATION	NOIDA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (ONE MONTH)
TYRE LIFE REMAINING (KM)	18,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

21,57,398




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Test Drive	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10

TOTAL ESTIMATE SPEND 18,500



Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score  **6/10**



21,57,398

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (YES)	7	GOOD	0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0

IMAGES



Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score



6/10



21,57,398



TEST DRIVE




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	ALTIMETAR NOISE	7000
IGNITION SYSTEM	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6	GOOD	0
REAR VIEW CAMERA (YES)	6	GOOD	0
SUSPENSION PERFORMANCE	5	STERING NOISE	7000



IMAGES




WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0
TYRES	5	GOOD	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0
ENGINE OIL	5	AVERAGE CONDITION	0

 IMAGES



Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score  **6/10**



21,57,398

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
LH FRONT DOOR	6	MINOR PAINTED	0
LH REAR DOOR	6	MINOR PAINTED	0
LH QUARTER PANEL	6	MINOR PAINTED	0
FUEL LID	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0
RH FRONT DOOR	6	GOOD	0
RH FENDER	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (SUN ROOF)	6	GOOD	0
PAINT CONDITION	6	GOOD	0
FRONT BUMPER	5	PAINTED	0
FOG LAMPS	0	NO	0
SIDE VIEW MIRRORS	5	SCRATCH	1500

Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score **6/10**




21,57,398

EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH FENDER	5	PAINTED	0
LH RUNNING BOARD	5	PAINTED AND SCRATCH	3000
REAR WINDSHIELD	5	ALREADY CHANGED	0
REAR BUMPER	5	PAINTED	0
RH QUARTER PANEL	5	PAINTED	0

IMAGES



DOCUMENTS



DESCRIPTION

car is better condition car minor painted car steering is minor noise altimeter noise

Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score




6/10



21,57,398

 IMAGES



Ordered by: Kshitij | Inspected date: 2018-12-01

Order Id: 32086

Overall Score



6/10



21,57,398

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.