

ECO INSPECTION CERTIFICATE

Premium

Order ID : 32429

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Sunny

Inspection Date :
2018-11-30

Valid Till :
2019-03-02

6/10

Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 102 does not need attention
- 2 Owners , 8 Years Vehicle Age
- 1 Accidental History Reported

Inspected By



Santosh Kumar

- Verified Technician**
- 607+ vehicle inspected
- 1+ years experience

Fiat Linea 1.3 MULTIJET DYNAMIC, 2010



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	LINEA	REGISTRATION NO.	DL4CAV5561
YEAR	2010	VIN/CHASIS NUMBER	9880GNZ
TRIM	1.3 MULTIJET DYNAMIC	KMS RUN	70089
COLOR	WHITE	INSURANCE EXPIRY	2018-11-30
BODY TYPE	SEDAN	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	YES	MAJOR ACCIDENT(S)	YES	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,29,987




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 16,050



Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score



6/10



2,29,987



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0



IMAGES



Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score **6/10**




2,29,987

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	3	BAD	1500

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0
ENGINE OIL	3	BAD	2500
COOLANT LEVEL	4	BAD	750

 IMAGES



Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score



6/10



2,29,987

 EXTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
LH RUNNING BOARD	6	MINOR PAINTED	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	5	PAINTED AND SCRATCH	3000
HEAD LIGHTS	3	RIGHT SIDE HED LIGHT IS BAD CONDITION	1800
HOOD	5	PAINTED	0
PILLAR	5	RIGHT QUTAR PAINAL ACCIDENT	0
SIDE VIEW MIRRORS	5	PAINTED AND SCRATCH	1000
LH FENDER	5	PAINTED AND MINOR SCRATCH	0
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED	0
LH QUARTER PANEL	5	PAINTED	0
REAR BUMPER	5	PAINTED AND SCRATCH	3000
BH QUARTER PANEL	5	PAINTED	0

Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score



6/10



2,29,987



EXTERIOR (CONTINUED)



5/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH RUNNING BOARD	5	PAINTED	0
RH REAR DOOR	5	PAINTED	0
RH FRONT DOOR	5	DENT	2500
RH FENDER	5	PAINTED	0
PAINT CONDITION	5	PAINTED	0



IMAGES



DOCUMENTS



DESCRIPTION

car is average condition need to be service car is 80% painted

Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score




6/10



2,29,987

IMAGES



REGN. NO : DL4CAV5561

REG. DT: 15/11/2010 O.SNO: 82 Registering Authority: Janakpur

CH. NO: MCAT102105001580002 REG. CD: FATEL COLOUR: B W WHITE

E. NO: 000780 CLASS: L.W.V.

NAME: SUNNY KATYAL SIND OF: PUNO BATHI KATYAL

ADDRESS: 8/11, SCA, TYPES STAFF QUARTER PASCHIM Vihar

DELHI 110000

MODEL: LINEA SALOON NO OF CYL: 4

WHEEL BASE: 2440MM UNLADEN WT: 1260

MPG/CITY: 0720/10 SEATING C: 5




FUEL: DIESEL STANDING C: 1248


REG. UPTO: 15/11/2020 CU. CAP: 1248

TAX UPTO: 01/11

PRODUCED UNDER LICENCE FROM
FIAT GROUP AUTOMOBILES S.P.A. ITALY
ENG. NO: 0927108
REG. NO: 09019880 8472
AUTOMOBILES LTD

PRODUCED UNDER LICENCE FROM
FIAT GROUP AUTOMOBILES S.P.A. ITALY
ENG. NO: 0927108
REG. NO: 09019880 8472
AUTOMOBILES LTD





Ordered by: sunny | Inspected date: 2018-11-30

Order Id: 32429

Overall Score



6/10



2,29,987

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.