

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 32619

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ajeet	Inspection Date : 2018-12-06	Valid Till : 2019-03-06
-----------------------	---------------------------------	----------------------------

## 6/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **102** does not need attention
- ✔ **3** Owners , **6** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ **Verified Technician**

630+ vehicle inspected  
1+ years experience

**Santosh Kumar**

## Nissan Micra XV PREMIUM DIESEL, 2012



VEHICLE INFORMATION			
MAKE	NISSAN	TRANSMISSION TYPE	MANUAL
MODEL	MICRA	REGISTRATION NO.	UP16AK6852
YEAR	2012	VIN/CHASIS NUMBER	5502024
TRIM	XV PREMIUM DIESEL	KMS RUN	65300
COLOR	WHITE	INSURANCE EXPIRY	2019-2-11
BODY TYPE	HATCHBACK	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
FLOOD DAMAGE	YES	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	YES	INSURANCE COPY AVAILABLE	YES (3RD PARTY)
		SERVICE LOGS AVAILABLE	YES (FULL)
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 2,36,147


Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

### ECO SCORE

Interior	<div style="width: 60%; background: yellow; height: 10px;"></div>	<b>6 / 10</b>
Wheel	<div style="width: 60%; background: yellow; height: 10px;"></div>	<b>6 / 10</b>
Test Drive	<div style="width: 60%; background: yellow; height: 10px;"></div>	<b>6 / 10</b>
Exterior	<div style="width: 60%; background: yellow; height: 10px;"></div>	<b>6 / 10</b>
Hood	<div style="width: 50%; background: orange; height: 10px;"></div>	<b>5 / 10</b>

### TOTAL ESTIMATE SPEND **75,100**



Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score  **6/10**




**2,36,147**

## INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR HINGES	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0
DOOR PANEL	5	NEED DRYCLINIG	2000
CARPET & FLOOR MAT	5	NEED DRYCLINIG	0
SEAT & SEAT BELT	4	BAD CONDITION	5000

## IMAGES



Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score  **6/10**



**2,36,147**

**NEED ATTENTION** ⚠️



**TEST DRIVE**

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
ENGINE NOISE	2	ENGINE IS BAD	60000
TRANSMISSION ENGAGE	3	ENGAGE	0

**IMAGES**



Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score



6/10



2,36,147

## WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	MINOR HARD	0
WHEEL ASSEMBLY (ALLOY RIM)	6	GOOD	0

## IMAGES





## HOOD



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
ENGINE OIL	3	BAD	2500
COOLANT LEVEL	4	BAD	600
EXHAUST SYSTEM	5	BLACK SMOKE	0

## IMAGES



Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score



6/10



2,36,147

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
LH FRONT DOOR	6	MINOR PAINTED	0
LH REAR DOOR	6	MINOR PAINTED	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH REAR DOOR	6	MINOR PAINTED	0
RH FRONT DOOR	6	MINOR PAINTED	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
FRONT BUMPER	5	PAINTED AND MINOR SCRATCH	0
FRONT WINDSHIELD	5	ALREADY CHANGED	0
SIDE VIEW MIRRORS	5	PAINTED AND SCRATCH	1000
LH FENDER	5	PAINTED	0
LH RUNNING BOARD	5	PAINTED AND DENT	3000
LH QUARTER PANEL	5	PAINTED	0

Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score



6/10




2,36,147

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
REAR BUMPER	5	PAINTED AND SCRATCH	1000
RH QUARTER PANEL	5	PAINTED	0
RH RUNNING BOARD	5	PAINTED	0
RH FENDER	5	PAINTED	0
PAINT CONDITION	5	40% PAINTED	0

IMAGES



NEED ATTENTION ⚠️





Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score



6/10



2,36,147



DOCUMENTS



DESCRIPTION

car is better canditon engine is major issues frant windshield is already changed 40% car painted

Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score




6/10



2,36,147

IMAGES



Ordered by: ajeet | Inspected date: 2018-12-06

Order Id: 32619

Overall Score



6/10



2,36,147

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.