

ECO INSPECTION CERTIFICATE

Premium

Order ID : 32715

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Karan	Inspection Date : 2018-12-06	Valid Till : 2019-03-06
-----------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **109** does not need attention
- ✔ **3** Owners , **9** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ Verified Technician

56+ vehicle inspected
1+ years experience

GAGAN GUPTA

Ford Endeavour 3.0L THUNDER PLUS 4X4, 2009



VEHICLE INFORMATION

MAKE	FORD	TRANSMISSION TYPE	MANUAL
MODEL	ENDEAVOUR	REGISTRATION NO.	HR70C7178
YEAR	2009	VIN/CHASIS NUMBER	9M12323
TRIM	3.0L THUNDER PLUS 4X4	KMS RUN	000000
COLOR	WHITE	INSURANCE EXPIRY	2018-12-4
BODY TYPE	OTHER	LOCATION	CHANDIGARH
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	4,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,51,879




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND **55,500**



Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score **7/10**



4,51,879

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	6		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	6		0

IMAGES



Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score **7/10**



4,51,879

NEED ATTENTION



TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	7		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	6		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score



7/10



4,51,879

WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	6	REFUSED	0

IMAGES



NEED ATTENTION



HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	REFUSED	0
RH APRON	6	REFUSED	0
RADIATOR	6		0
WIRING	6	REFUSED	0
BATTERY	6	REFUSED	0
BRAKE FLUID LEVEL	6		0

ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



 NEED ATTENTION 



Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score  **7/10**



4,51,879

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	REFUSED	0
HEAD LIGHTS	7	REFUSED	0
TURN SIGNAL	7	REFUSED	0
FOG LAMPS	7	REFUSED	0
PILLAR	7	REFUSED	0
FRONT WINDSHIELD	7	REFUSED	0
SIDE VIEW MIRRORS	6	REFUSED	0
FUEL LID	7	REFUSED	0
LUGGAGE COMPARTMENT LIGHT	6	REFUSED	0
RH QUARTER PANEL	7	REFUSED	0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0
RH FENDER	7	REFUSED	0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
FRONT BUMPER	5	REFUSED	6000
GRILLE	5	SCRATCHED	5000
HOOD	5	REFUSED	5000
LH FENDER	4	REFUSED	4000
LH FRONT DOOR	4	REFUSED	4000
LH REAR DOOR	4	REFUSED	4000
LH RUNNING BOARD	4	REFUSED	4000

Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score



7/10



4,51,879



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH QUARTER PANEL	4	REFUSED	5000
REAR WINDSHIELD	4	REFUSED	6000
REAR BUMPER	4	REFUSED BCZ DAMAGES	6000
TAIL LIGHT	4	REFUSED BCZ DAMAGES	2500
TRUNK LID/TAIL GATE	4	REFUSED BCZ DAMAGES	4000




IMAGES



NEED ATTENTION





 **DOCUMENTS**



 **DESCRIPTION**

average

Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score







7/10



4,51,879

 IMAGES





Ordered by: karan | Inspected date: 2018-12-06

Order Id: 32715

Overall Score



7/10



4,51,879



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.