

ECO INSPECTION CERTIFICATE

Premium

Order ID : 33171

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Kp	Inspection Date : 2018-12-07	Valid Till : 2019-03-07	Inspected By Verified Technician 633+ vehicle inspected 1+ years experience Santosh Kumar
<h2>7/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> Evaluated across 5 segments Covered 121+ checkpoints 116 does not need attention 1 Owner , 5 Years Vehicle Age No Accidental History 	

Nissan Terrano XV D THP 110 PS, 2013



VEHICLE INFORMATION

MAKE	NISSAN	TRANSMISSION TYPE	MANUAL
MODEL	TERRANO	REGISTRATION NO.	UP14CC1600
YEAR	2013	VIN/CHASIS NUMBER	B002475
TRIM	XV D THP 110 PS	KMS RUN	25259
COLOR	SILVER	INSURANCE EXPIRY	2018-12-11
BODY TYPE	SUV	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,73,503




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score **7/10**





6,73,503

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

IMAGES



Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score **7/10**



6,73,503

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (YES)	7	GOOD	0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	GOOD	0
WIRING	7	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score  **7/10**



6,73,503

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	MINOR SCRATCH	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	6	MINOR SCRATCH	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0

Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score **7/10**



6,73,503

EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH FENDER	5	PAINTED	0
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED	0
LH QUARTER PANEL	5	PAINTED	0
RH QUARTER PANEL	5	PAINTED	0

IMAGES



NEED ATTENTION ⚠



Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score






7/10



6,73,503

 DOCUMENTS



 DESCRIPTION

car is better canditon left side both full painted

Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score




7/10



6,73,503

IMAGES



Ordered by: Kp | Inspected date: 2018-12-07

Order Id: 33171

Overall Score



7/10



6,73,503

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.