



# ECO INSPECTION CERTIFICATE

Premium

Order ID : 33428

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sanjay	Inspection Date : 2018-12-08	Valid Till : 2019-03-08	 Inspected By   Manoj Kumar
------------------------	---------------------------------	----------------------------	--

8/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

234+ vehicle inspected  
1+ years experience










## Audi A4 2.0 TDI 177 BHP PREMIUM PLUS, 2014



### VEHICLE INFORMATION

MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A4	REGISTRATION NO.	HR26CF2607
YEAR	2014	VIN/CHASIS NUMBER	700880
TRIM	2.0 TDI 177 BHP PREMIUM PLUS	KMS RUN	47435
COLOR	BLUE	INSURANCE EXPIRY	2019-3-31
BODY TYPE	OTHER	LOCATION	SEC 66
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (FULL)
 TYRE LIFE REMAINING (KM)	45,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

22,39,359




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 80%;"></div>	9 / 10
 Wheel	<div style="width: 80%;"></div>	9 / 10
 Test Drive	<div style="width: 70%;"></div>	8 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score



8/10



22,39,359



## INTERIOR



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	9	GOOD	0
SPEAKERS & MUSIC SYSTEM	9	GOOD	0
HANDBRAKE	9	GOOD	0
STEERING-MOUNTED CONTROLS	9	GOOD	0
PEDALS	9	GOOD	0
CENTRAL LOCK	9	GOOD	0
A/C VENTS & HEATER	9	GOOD	0
CUP HOLDERS	9	GOOD	0
NAVIGATION (YES)	9	GOOD	0
ODOMETER	9	GOOD	0
POWER WINDOWS (YES)	9	GOOD	0
HAZARD LIGHT	9	GOOD	0

## IMAGES



Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score



8/10



22,39,359



## TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	8	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0
CRUISE CONTROL (YES)	8	GOOD	0
REAR PARKING SENSORS (YES)	8	GOOD	0
REAR VIEW CAMERA (YES)	8	GOOD	0



## IMAGES



## WHEEL



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	9	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	9	GOOD	0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	9	GOOD	0
BATTERY	9	GOOD	0
BRAKE FLUID LEVEL	9	GOOD	0
ENGINE OIL	9	GOOD	0
COOLANT LEVEL	9	GOOD	0
BRAKE & COOLANT HOSE PIPES	8	GOOD	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

 IMAGES



Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score



8/10



22,39,359

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	8	GOOD	0
HEAD LIGHTS	8	GOOD	0
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	8	GOOD	0
TAIL LIGHT	8	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOOD	0



Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score



8/10



22,39,359



## EXTERIOR (CONTINUED)






8/10








INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD	0
RH FENDER	8	GOOD	0
BODY RUST	8	GOOD	0
ROOF (SUN ROOF)	8	GOOD	0
PAINT CONDITION	8	GOOD	0




## IMAGES




## NEED ATTENTION







## DOCUMENTS



## DESCRIPTION

vehicle condition is good all tyres already changed



Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score




8/10




22,39,359

IMAGES







Ordered by: Sanjay | Inspected date: 2018-12-08

Order Id: 33428

Overall Score



8/10



22,39,359

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.