

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 33513

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Romit	Inspection Date : 2018-12-06	Valid Till : 2019-03-06
-----------------------	---------------------------------	----------------------------

## 7/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

**Inspected By**



**Verified Technician**  
276+ vehicle inspected  
1+ years experience

Sourav Biswas

## Tata Tiago REVOTORQ XZ, 2017



VEHICLE INFORMATION			
MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	TIAGO	REGISTRATION NO.	WB24AM3276
YEAR	2017	VIN/CHASIS NUMBER	NA
TRIM	REVOTORQ XZ	KMS RUN	20506
COLOR	OTHER	INSURANCE EXPIRY	2018-12-6
BODY TYPE	SEDAN	LOCATION	SODEPUR
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

## KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	YES



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 4,88,940



Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

### ECO SCORE

Interior	<div style="width: 80%; background: green;"></div>	8 / 10
Wheel	<div style="width: 80%; background: green;"></div>	8 / 10
Test Drive	<div style="width: 80%; background: green;"></div>	8 / 10
Exterior	<div style="width: 70%; background: green;"></div>	7 / 10
Hood	<div style="width: 70%; background: green;"></div>	7 / 10

### TOTAL ESTIMATE SPEND 0

0

Interior

0

Wheel

0

Test Drive

0

Exterior

0

Hood

Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score  **7/10**




**4,88,940**

## INTERIOR

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	OK	0
DOOR HINGES	8	OK	0
CARPET & FLOOR MAT	7	OK	0
SEAT & SEAT BELT	8	OK	0
DASHBOARD & INSTRUMENT PANEL	8	OK	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	8	OK	0
HANDBRAKE	8	OK	0
STEERING-MOUNTED CONTROLS	8	OK	0
PEDALS	8	OK	0
CENTRAL LOCK	7	OK	0
A/C VENTS & HEATER	7	OK	0
CUP HOLDERS	7	OK	0
NAVIGATION (NO)	10		0
ODOMETER	7	OK	0
POWER WINDOWS (YES)	7	OK	0
HAZARD LIGHT	7	OK	0

## IMAGES



Ordered by: Romit | Inspected date: 2018-12-06


Order Id: 33513

Overall Score  **7/10**



**4,88,940**

**NEED ATTENTION** ⚠️



**TEST DRIVE**

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	OK	0
BRAKE PERFORMANCE	8	OK	0
CLUTCH PERFORMANCE	7	OK	0
ENGINE NOISE	7	OK	0
IGNITION SYSTEM	7	OK	0
SUSPENSION PERFORMANCE	8	OK	0
SUSPENSION FRONT SHOCKS	8	OK.	0
SUSPENSION REAR SHOCKS	7	OK	0
TRANSMISSION ENGAGE	7	OK	0
CRUISE CONTROL (YES)	7	OK	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

**IMAGES**



Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score  **7/10**




**4,88,940**

## WHEEL


**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	OK	0
SPARE TYRE (YES)	7	OK.	0
WHEEL ASSEMBLY (STEEL RIM)	8	OK	0

## IMAGES



## NEED ATTENTION




## HOOD

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	OK	0
RH APRON	8	OK	0
RADIATOR	7	OK	0
WIRING	7	OK	0
BATTERY	8	OK	0
BRAKE FLUID LEVEL	8	OK	0

ENGINE OIL	8	OK	0
COOLANT LEVEL	8	OK	0
BRAKE & COOLANT HOSE PIPES	7	OK	0
UNDERCARRIAGE	7	OK	0
EXHAUST SYSTEM	7	OK	0

## IMAGES



Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score  **7/10**



**4,88,940**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	OK	0
FRONT BUMPER	7	OK	0
HEAD LIGHTS	7	OK	0
GRILLE	7	OK.	0
TURN SIGNAL	7	OK	0
FOG LAMPS	7	OK	0
HOOD	7	OK	0
PILLAR	7	OK	0
FRONT WINDSHIELD	7	OK	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	7	OK	0
LH FRONT DOOR	7	OK	0
LH REAR DOOR	7	OK	0
LH RUNNING BOARD	7	OK	0
LH QUARTER PANEL	8	OK	0
FUEL LID	7	OK	0
REAR WINDSHIELD	7	OK	0
REAR BUMPER	7	OK	0
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	7	OK	0
LUGGAGE COMPARTMENT LIGHT	7	OK	0
RH QUARTER PANEL	7	OK	0
RH RUNNING BOARD	7	OK	0
RH REAR DOOR	7	OK	0



Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score  **7/10**



**4,88,940**

**EXTERIOR (CONTINUED)**

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	OK	0
RH FENDER	7	OK	0
BODY RUST	7	OK	0
ROOF (REGULAR)	7	OK	0
PAINT CONDITION	8	OK	0

**IMAGES**



**NEED ATTENTION** ⚠️





## DESCRIPTION

Good condition



Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score




7/10








4,88,940

IMAGES







Ordered by: Romit | Inspected date: 2018-12-06

Order Id: 33513

Overall Score



7/10



4,88,940

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.