

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 33596

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sarthak	Inspection Date : 2018-12-09	Valid Till : 2019-03-09
-------------------------	---------------------------------	----------------------------

## 7/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ **Verified Technician**

177+ vehicle inspected

1+ years experience

**Bimal Vivek**

## Nissan Micra XE DIESEL, 2014



VEHICLE INFORMATION			
MAKE	NISSAN	TRANSMISSION TYPE	MANUAL
MODEL	MICRA	REGISTRATION NO.	DL1CS1562
YEAR	2014	VIN/CHASIS NUMBER	MDHFCUK13D9704378
TRIM	XE DIESEL	KMS RUN	34903
COLOR	RED	INSURANCE EXPIRY	2019-6-20
BODY TYPE	HATCHBACK	LOCATION	PATEL NAGAR 2ND
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	13,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 3,02,322

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE	TOTAL ESTIMATE SPEND 0
<ul style="list-style-type: none"> <li> Interior <span style="float: right;">7 / 10</span></li> <li> Wheel <span style="float: right;">7 / 10</span></li> <li> Test Drive <span style="float: right;">8 / 10</span></li> <li> Exterior <span style="float: right;">7 / 10</span></li> <li> Hood <span style="float: right;">7 / 10</span></li> </ul>	

Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score



7/10



3,02,322



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	6	NA	0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7	LH BUTTON WORKONG PROPERLY	0
HAZARD LIGHT	7		0



## IMAGES



Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score  **7/10**



**3,02,322**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score  **7/10**



**3,02,322**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7	MINOR SCRATCHES	0
HEAD LIGHTS	8		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	6	NEED RUSTING	0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	8		0
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	8	MINOR SCRATCHES	0
TAIL LIGHT	6	RH TAIL LIGHT BROCKEN	0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	8		0

Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score



7/10



3,02,322



**EXTERIOR (CONTINUED)**




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	7		0
PAINT CONDITION	8		0



**IMAGES**



**NEED ATTENTION**



Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score




7/10



3,02,322



DOCUMENTS



DESCRIPTION

car is in vey good condition

Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score




7/10



3,02,322

IMAGES





Ordered by: Sarthak | Inspected date: 2018-12-09

Order Id: 33596

Overall Score



7/10



3,02,322

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.