

ECO INSPECTION CERTIFICATE

Premium

Order ID : 34100

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Prashant	Inspection Date : 2018-12-10	Valid Till : 2019-03-10
--------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **115** does not need attention
- ✔ **2** Owners , **5** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

281+ vehicle inspected

1+ years experience

Sourav Biswas

Tata Indica Ev2 LX, 2013



VEHICLE INFORMATION

MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	INDICA EV2	REGISTRATION NO.	WB04F5859
YEAR	2013	VIN/CHASIS NUMBER	NA
TRIM	LX	KMS RUN	100000
COLOR	WHITE	INSURANCE EXPIRY	2018-12-10
BODY TYPE	SEDAN	LOCATION	HARIDEVPUR
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	6,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,90,965




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10

TOTAL ESTIMATE SPEND 42,000



Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score



6/10



1,90,965



INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	6	OK	0
CARPET & FLOOR MAT	6	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	7	OK	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	7	OK	0
HANDBRAKE	7	OK	0
STEERING-MOUNTED CONTROLS	7	OK	0
PEDALS	6	OK	0
CENTRAL LOCK	6	NA	0
A/C VENTS & HEATER	6	OK	0
CUP HOLDERS	6	AVAILABLE	0
NAVIGATION (NO)	10		0
ODOMETER	6	AVERAGE	0
POWER WINDOWS (YES - FRONT ONLY)	6	AVERAGE	0
HAZARD LIGHT	6	OK	0



IMAGES



Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score **6/10**



1,90,965

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE	0
BRAKE PERFORMANCE	6	OK	0
CLUTCH PERFORMANCE	6	OK	0
ENGINE NOISE	6	OK	0
IGNITION SYSTEM	6	OK	0
SUSPENSION PERFORMANCE	6	OK	0
SUSPENSION FRONT SHOCKS	6	OK	0
SUSPENSION REAR SHOCKS	6	OK	0
TRANSMISSION ENGAGE	6	NA	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE (YES)	6	OK	0
WHEEL ASSEMBLY (STEEL RIM)	6	OK	0

 IMAGES

 HOOD


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE	0
RH APRON	6	AVERAGE	0
RADIATOR	6	OK	0
WIRING	6	AVERAGE	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	6	OK	0
ENGINE OIL	6	AVERAGE	0
COOLANT LEVEL	6	OK	0
BRAKE & COOLANT HOSE PIPES	6	OK	0
UNDERCARRIAGE	6	AVERAGE	0
EXHAUST SYSTEM	7	OK	0

 IMAGES


Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score  **6/10**



1,90,965

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	6	AVERAGE	0
GRILLE	6	AVERAGE	0
TURN SIGNAL	6	OK	0
FOG LAMPS	6	NA	0
HOOD	6	AVERAGE	0
PILLAR	6	AVERAGE	0
FRONT WINDSHIELD	6	OK	0
SIDE VIEW MIRRORS	6	OK	0
LH REAR DOOR	6	AVERAGE	0
LH RUNNING BOARD	6	OK	0
FUEL LID	6	OK	0
REAR WINDSHIELD	6	OK	0
REAR BUMPER	6	AVERAGE	0
TAIL LIGHT	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
LUGGAGE COMPARTMENT LIGHT	6	OK	0
RH QUARTER PANEL	6	OK	0
RH RUNNING BOARD	6	AVERAGE	0
RH REAR DOOR	6	AVERAGE	0
RH FRONT DOOR	6	AVERAGE	0
RH FENDER	6	AVERAGE	0
BODY RUST	6	AVERAGE	0
ROOF (REGULAR)	6	OK	0
LICENSE PLATE	5	NEED TO REPLACE	1000

Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score **6/10**



1,90,965

EXTERIOR (CONTINUED)


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	5	NEED TO REPAIR	3000
LH FENDER	4	DENT	3000
LH FRONT DOOR	5	DENT	4000
LH QUARTER PANEL	5	DENT	1000
PAINT CONDITION	5	REQUIRED	30000

IMAGES



NEED ATTENTION ⚠





DESCRIPTION

Average

Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score




6/10



1,90,965

IMAGES



Ordered by: Prashant | Inspected date: 2018-12-10

Order Id: 34100

Overall Score



6/10



1,90,965

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.