

ECO INSPECTION CERTIFICATE

Premium

Order ID : 34511

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Megha	Inspection Date : 2018-12-24	Valid Till : 2019-03-24	Inspected By Pawan Kumar Gupta
-----------------------	---------------------------------	----------------------------	--

7/10
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 120 does not need attention
- 1 Owner , 1 Year Vehicle Age
- No Accidental History

Verified Technician
90+ vehicle inspected
1+ years experience

Mahindra Kuv100 Nxt K8 D 6 STR DUAL TONE, 2017



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	KUV100 NXT	REGISTRATION NO.	PB10GR5125
YEAR	2017	VIN/CHASIS NUMBER	87454
TRIM	K8 D 6 STR DUAL TONE	KMS RUN	15460
COLOR	OTHER	INSURANCE EXPIRY	2019-12-19
BODY TYPE	OTHER	LOCATION	LUDHIANA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	5,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE (BUMPER TO BUMPER)	YES
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,43,254

Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
Interior	7 / 10	8,000
Wheel	8 / 10	
Test Drive	7 / 10	
Exterior	7 / 10	
Hood	7 / 10	

Bar chart showing repair cost estimates for Interior (0), Wheel (0), Test Drive (0), Exterior (8,000), and Hood (0).

Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score  **7/10**



6,43,254

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	6		0

IMAGES



Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score **7/10**



6,43,254

NEED ATTENTION




TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	7		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (YES)	7		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score



7/10



6,43,254


WHEEL




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

IMAGES



NEED ATTENTION ⚠



HOOD



7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	8		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0

ENGINE OIL	7		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	6		0

IMAGES



NEED ATTENTION



Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score  **7/10**



6,43,254

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	8		0
FOG LAMPS	6		0
HOOD	7		0
PILLAR	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	8		0

Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score **7/10**



6,43,254

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0
FRONT WINDSHIELD	5	SCAR	8000

IMAGES





NEED ATTENTION ⚠️





 DOCUMENTS



 DESCRIPTION

good

Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score










7/10



6,43,254

IMAGES





Ordered by: Megha | Inspected date: 2018-12-24

Order Id: 34511

Overall Score



7/10



6,43,254

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.