


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 35376

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Naman	Inspection Date : 2018-12-20	Valid Till : 2019-03-21	Inspected By  Manoj Kumar
-----------------------	---------------------------------	----------------------------	--

8/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **5** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

284+ vehicle inspected  
1+ years experience

## Volvo Xc90 D5 AWD, 2013



### VEHICLE INFORMATION

MAKE	VOLVO	TRANSMISSION TYPE	AUTOMATIC
MODEL	XC90	REGISTRATION NO.	HR26CA6420
YEAR	2013	VIN/CHASIS NUMBER	662724
TRIM	D5 AWD	KMS RUN	86828
COLOR	OTHER	INSURANCE EXPIRY	2019-6-3
BODY TYPE	SUV	LOCATION	DLF PHASE 2
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	48,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	YES
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

29,81,235




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235



## INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD CONDITION	0
DOOR HINGES	8	GOOD CONDITION	0
CARPET & FLOOR MAT	8	GOOD CONDITION	0
SEAT & SEAT BELT	8	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION	0
HORN	8	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION	0
HANDBRAKE	8	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	GOOD CONDITION	0
PEDALS	8	GOOD CONDITION	0
CENTRAL LOCK	8	GOOD CONDITION	0
A/C VENTS & HEATER	8	GOOD CONDITION	0
CUP HOLDERS	8	GOOD CONDITION	0
NAVIGATION (YES)	8	GOOD CONDITION	0
ODOMETER	8	GOOD CONDITION	0
POWER WINDOWS (YES)	8	GOOD CONDITION	0
HAZARD LIGHT	8	GOOD CONDITION	0



## IMAGES



Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235



NEED ATTENTION



TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD CONDITION	0
BRAKE PERFORMANCE	8	GOOD CONDITION	0
CLUTCH PERFORMANCE	8	GOOD CONDITION	0
ENGINE NOISE	8	GOOD CONDITION	0
IGNITION SYSTEM	8	GOOD CONDITION	0
SUSPENSION PERFORMANCE	8	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	8	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	8	GOOD CONDITION	0
TRANSMISSION ENGAGE	8	GOOD CONDITION	0
CRUISE CONTROL (YES)	8	GOOD CONDITION	0
REAR PARKING SENSORS (YES)	8	GOOD CONDITION	0
REAR VIEW CAMERA (YES)	8	GOOD CONDITION	0



IMAGES



Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235

## WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD CONDITION	0
SPARE TYRE (YES)	8	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	8	GOOD CONDITION	0

## IMAGES




## HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD CONDITION	0
RH APRON	9	GOOD CONDITION	0
RADIATOR	8	GOOD CONDITION	0
WIRING	8	GOOD CONDITION	0
BATTERY	8	GOOD CONDITION	0
BRAKE FLUID LEVEL	8	GOOD CONDITION	0
ENGINE OIL	8	GOOD CONDITION	0
COOLANT LEVEL	8	GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	8	GOOD CONDITION	0
UNDERCARRIAGE	8	GOOD CONDITION	0
EXHAUST SYSTEM	8	GOOD CONDITION	0

## IMAGES



Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHES	0
HEAD LIGHTS	8	GOOD CONDITION	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION	0
FOG LAMPS	8	GOOD CONDITION	0
HOOD	8	GOOD CONDITION	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	8	GOOD CONDITION	0
SIDE VIEW MIRRORS	8	GOOD CONDITION	0
LH FENDER	8	GOOD CONDITION	0
LH FRONT DOOR	8	GOOD CONDITION	0
LH REAR DOOR	6	MINOR SCRATCHES	0
LH RUNNING BOARD	8	GOOD CONDITION	0
LH QUARTER PANEL	8	GOOD CONDITION	0
FUEL LID	8	GOOD CONDITION	0
REAR WINDSHIELD	8	GOOD CONDITION	0
REAR BUMPER	8	GOOD CONDITION	0
TAIL LIGHT	8	GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD CONDITION	0
RH QUARTER PANEL	8	GOOD CONDITION	0
RH RUNNING BOARD	8	GOOD CONDITION	0
RH REAR DOOR	8	GOOD CONDITION	0

Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235



## EXTERIOR (CONTINUED)





8/10





INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD CONDITION	0
RH FENDER	8	GOOD CONDITION	0
BODY RUST	8	GOOD CONDITION	0
ROOF (SUN ROOF)	8	GOOD CONDITION	0
PAINT CONDITION	8	GOOD CONDITION	0




## IMAGES




## NEED ATTENTION





## DOCUMENTS



## DESCRIPTION

minor scratches and minor dent all tyres already changed



Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score









8/10



29,81,235

IMAGES





Ordered by: Naman | Inspected date: 2018-12-20

Order Id: 35376

Overall Score



8/10



29,81,235

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.