


ECO INSPECTION CERTIFICATE

Premium

Order ID : 35966

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Siddhartha	Inspection Date : 2018-12-29	Valid Till : 2019-03-29	Inspected By  Manoj Kumar
----------------------------	---------------------------------	----------------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History










✔ **Verified Technician**

308+ vehicle inspected
1+ years experience

Tata Safari 4X2 EX DICOR 2.2 VTT, 2009



VEHICLE INFORMATION			
MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	SAFARI	REGISTRATION NO.	KA05MH1384
YEAR	2009	VIN/CHASIS NUMBER	07228
TRIM	4X2 EX DICOR 2.2 VTT	KMS RUN	92864
COLOR	SILVER	INSURANCE EXPIRY	2018-12-19
BODY TYPE	OTHER	LOCATION	SEC 50
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (FULL)
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:






3,22,002



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%; height: 10px; background: linear-gradient(to right, #00a651, #ccc);"></div>	7 / 10
 Wheel	<div style="width: 75%; height: 10px; background: linear-gradient(to right, #00a651, #ccc);"></div>	7 / 10
 Test Drive	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #00a651, #ccc);"></div>	8 / 10
 Exterior	<div style="width: 70%; height: 10px; background: linear-gradient(to right, #00a651, #ccc);"></div>	7 / 10
 Hood	<div style="width: 70%; height: 10px; background: linear-gradient(to right, #00a651, #ccc);"></div>	7 / 10

TOTAL ESTIMATE SPEND 0


0


0


0


0


0

 Interior

 Wheel

 Test Drive

 Exterior

 Hood

Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score **7/10**



3,22,002

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NA	0

IMAGES



Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score **7/10**



3,22,002

NEED ATTENTION ⚠️




TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score **7/10**



3,22,002

WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

IMAGES





HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

IMAGES



Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score  **7/10**



3,22,002

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	6	MINOR SCRATCHES	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	6	MINOR SCRATCHES	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	6	MINOR SCRATCHES	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	6	MINOR SCRATCHES	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	6	MINOR SCTATCHES	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	6	MINOR SCRATCHES	0

Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score **7/10**



3,22,002

EXTERIOR (CONTINUED)


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0

IMAGES




NEED ATTENTION ⚠️





 DOCUMENTS



 DESCRIPTION

minor scratches and minor dent all tyres cracking need to be changed front bumper and Hood already p

Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score


















7/10



3,22,002

IMAGES





Ordered by: Siddhartha | Inspected date: 2018-12-29

Order Id: 35966

Overall Score



7/10



3,22,002

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.