


ECO INSPECTION CERTIFICATE

Premium

Order ID : 38286

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ashish	Inspection Date : 2019-01-28	Valid Till : 2019-04-29	Inspected By  Pawan Kumar Gupta
------------------------	---------------------------------	----------------------------	--------------------------------------------------------------------------------------------------------------------------

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
128+ vehicle inspected
1+ years experience

Mercedes-Benz C-Class 220 Cdi Avantgarde At, 2014



VEHICLE INFORMATION

MAKE	MERCEDES-BENZ	TRANSMISSION TYPE	MANUAL
MODEL	C-CLASS	REGISTRATION NO.	HR26CH1502
YEAR	2014	VIN/CHASIS NUMBER	72975
TRIM	220 CDI AVANTGARDE AT	KMS RUN	89184
COLOR	SILVER	INSURANCE EXPIRY	2019-6-20
BODY TYPE	SEDAN	LOCATION	GURGAON
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	3,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

22,53,689




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score **7/10**



22,53,689

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	OK	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	7	WORKING	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	7	WORKING	0
HANDBRAKE	7	OK	0
STEERING-MOUNTED CONTROLS	7	OK	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	OK	0
A/C VENTS & HEATER	7	WORKING	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (YES)	7	OK	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	6	OK	0
HAZARD LIGHT	7	WORKING	0

IMAGES



Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score **7/10**



22,53,689

NEED ATTENTION ⚠️



TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	OK	0
ENGINE NOISE	6	LESS NOISE	0
IGNITION SYSTEM	7	OK	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	OK	0
TRANSMISSION ENGAGE	7	SMOOTH	0
CRUISE CONTROL (YES)	6	OK	0
REAR PARKING SENSORS (YES)	6	GOOD	0
REAR VIEW CAMERA (YES)	7	GOOD	0

IMAGES



Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score



7/10



22,53,689


WHEEL




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

IMAGES



NEED ATTENTION ⚠



HOOD




7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	OK	0
WIRING	7	GOOD	0
BATTERY	7	OK	0
BRAKE FLUID LEVEL	7	ABOVE AVERAGE	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	ABOVE AVERAGE	0
BRAKE & COOLANT HOSE PIPES	6	OK	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	7	BETTER	0

IMAGES



NEED ATTENTION



Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score  **7/10**



22,53,689

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	NO DAMAGE	0
FRONT BUMPER	6	NO DAMAGE	0
HEAD LIGHTS	7	WORKING	0
GRILLE	7	OK	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	7	WORKING	0
HOOD	7	OK	0
PILLAR	7	OK	0
FRONT WINDSHIELD	7	SMOOTH	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	7	NO DAMAGE	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	OK	0
REAR WINDSHIELD	7	SMOOTH	0
REAR BUMPER	7	NO DAMAGE	0
TAIL LIGHT	7	OK	0
TRUNK LID/TAIL GATE	7	OK	0
LUGGAGE COMPARTMENT LIGHT	7	OK	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	NO DAMAGE	0
RH REAR DOOR	7	GOOD	0

Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score **7/10**



22,53,689

EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD	0
RH FENDER	8	OK	0
BODY RUST	7	NO BODY RUST	0
ROOF (REGULAR)	7	SMOOTH	0
PAINT CONDITION	7	GOOD	0

IMAGES




NEED ATTENTION ⚠️





 DOCUMENTS



 DESCRIPTION

good

Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score











7/10



22,53,689

IMAGES





Ordered by: ashish | Inspected date: 2019-01-28

Order Id: 38286

Overall Score



7/10



22,53,689

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.