

ECO INSPECTION CERTIFICATE

Premium

Order ID : 38312

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Mudit

Inspection Date :
2019-01-17

Valid Till :
2019-04-17

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Gagan
Gurawaliya

- ✓ Verified Technician
- 372+ vehicle inspected
- 1+ years experience










Audi A4 35 TDI TECHNOLOGY, 2017



VEHICLE INFORMATION

MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A4	REGISTRATION NO.	HR26DH0564
YEAR	2017	VIN/CHASIS NUMBER	702004
TRIM	35 TDI TECHNOLOGY	KMS RUN	14733
COLOR	BLACK	INSURANCE EXPIRY	2019-12-9
BODY TYPE	SEDAN	LOCATION	SEC7MANESHARGGN
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (FULL)
 TYRE LIFE REMAINING (KM)	50,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

39,11,445




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div></div>	8 / 10
 Wheel	<div></div>	8 / 10
 Test Drive	<div></div>	8 / 10
 Exterior	<div></div>	8 / 10
 Hood	<div></div>	8 / 10

TOTAL ESTIMATE SPEND 4,000



Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score



8/10



39,11,445



INTERIOR






8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD CONDITION AND WORKING PROPERLY	0
DOOR HINGES	8	GOOD CONDITION AND WORKING PROPERLY	0
CARPET & FLOOR MAT	8	GOOD CONDITION	0
SEAT & SEAT BELT	8	GOOD CONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION AND WORKING PROPERLY	0
HORN	8	GOOD CONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION AND WORKING PROPERLY	0
HANDBRAKE	8	GOOD CONDITION AND WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	8	GOOD CONDITION AND WORKING PROPERLY	0
PEDALS	8	GOOD CONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	8	GOOD CONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	8	GOOD CONDITION AND WORKING PROPERLY	0
CUP HOLDERS	8	GOOD CONDITION	0
NAVIGATION (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
ODOMETER	8	GOOD CONDITION AND WORKING PROPERLY	0
POWER WINDOWS (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	8	GOOD CONDITION AND WORKING PROPERLY	0



IMAGES



Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score

8/10



39,11,445




TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
CLUTCH PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
ENGINE NOISE	8	NORMAL SOUND	0
IGNITION SYSTEM	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	8	GOOD CONDITION AND WORKING PROPERLY	0
TRANSMISSION ENGAGE	8	GOOD CONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
REAR PARKING SENSORS (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
REAR VIEW CAMERA (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0



IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD CONDITION AND WORKING PROPERLY	0
SPARE TYRE (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
WHEEL ASSEMBLY (ALLOY RIM)	8	GOOD CONDITION AND WORKING PROPERLY	0

IMAGES






HOOD

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD CONDITION	0
RH APRON	8	GOOD CONDITION	0
RADIATOR	8	GOOD CONDITION AND WORKING PROPERLY	0
WIRING	8	GOOD CONDITION AND WORKING PROPERLY	0
BATTERY	8	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE FLUID LEVEL	8	MAXIMUM	0
ENGINE OIL	8	MAXIMUM	0
COOLANT LEVEL	8	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	8	GOOD CONDITION AND WORKING PROPERLY	0
UNDERCARRIAGE	8	GOOD CONDITION	0
EXHAUST SYSTEM	8	GOOD CONDITION AND WORKING PROPERLY	0

IMAGES



Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score



8/10



39,11,445



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD CONDITION	0
FRONT BUMPER	7	MINOR SCRATCHES	2000
HEAD LIGHTS	8	GOOD CONDITION AND WORKING PROPERLY	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION AND WORKING PROPERLY	0
FOG LAMPS	8	GOOD CONDITION AND WORKING PROPERLY	0
HOOD	8	GOOD CONDITION AND WORKING PROPERLY	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	8	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	8	GOOD CONDITION AND WORKING PROPERLY	0
LH FENDER	8	GOOD CONDITION	0
LH FRONT DOOR	8	GOOD CONDITION	0
LH REAR DOOR	8	GOOD CONDITION	0
LH RUNNING BOARD	8	GOOD CONDITION	0
LH QUARTER PANEL	8	GOOD CONDITION	0
FUEL LID	8	GOOD CONDITION AND WORKING PROPERLY	0
REAR WINDSHIELD	8	GOOD VISIBILITY	0
REAR BUMPER	7	MINOR SCRATCHES	2000
TAIL LIGHT	8	GOOD CONDITION AND WORKING PROPERLY	0
TRUNK LID/TAIL GATE	8	GOOD CONDITION AND WORKING PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD CONDITION	0

RH QUARTER PANEL	8	GOOD CONDITION	0
RH RUNNING BOARD	8	GOOD CONDITION	0
RH REAR DOOR	8	GOOD CONDITION	0

Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score



8/10



39,11,445



EXTERIOR (CONTINUED)









8/10






INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD CONDITION	0
RH FENDER	8	GOOD CONDITION	0
BODY RUST	8	GOOD CONDITION	0
ROOF (SUN ROOF)	8	GOOD CONDITION AND WORKING PROPERLY	0
PAINT CONDITION	8	GOOD CONDITION	0



IMAGES




NEED ATTENTION ⚠





DOCUMENTS



DESCRIPTION

minor scratches both rear tyres are already changed

Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score



















8/10



39,11,445

IMAGES





Ordered by: Mudit | Inspected date: 2019-01-17

Order Id: 38312

Overall Score



8/10



39,11,445



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.