


ECO INSPECTION CERTIFICATE

Premium

Order ID : 38495

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gaurav	Inspection Date : 2019-01-14	Valid Till : 2019-04-14	Inspected By  Gagan Gurawaliya
------------------------	---------------------------------	----------------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **3** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

362+ vehicle inspected
1+ years experience

Volkswagen Polo GT TSI, 2016



VEHICLE INFORMATION			
MAKE	VOLKSWAGEN	TRANSMISSION TYPE	AUTOMATIC
MODEL	POLO	REGISTRATION NO.	HR26DA3783
YEAR	2016	VIN/CHASIS NUMBER	086541
TRIM	GT TSI	KMS RUN	17063
COLOR	RED	INSURANCE EXPIRY	2019-11-12
BODY TYPE	HATCHBACK	LOCATION	SEC45GGN
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	YES (DUPLICATE)
DENT	NO	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)
		SERVICE LOGS AVAILABLE	YES (FULL)
		BANK HYPOTHECATION	NO
		BANK NOC	NO




Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

6,63,584



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
Interior <div style="width: 100px; height: 10px; background: linear-gradient(to right, green 70%, gray 30%);"></div> 7 / 10	Wheel <div style="width: 100px; height: 10px; background: linear-gradient(to right, green 70%, gray 30%);"></div> 7 / 10	<div style="text-align: center;"> <p>500</p>  </div>
Test Drive <div style="width: 100px; height: 10px; background: linear-gradient(to right, green 80%, gray 20%);"></div> 8 / 10	Exterior <div style="width: 100px; height: 10px; background: linear-gradient(to right, green 70%, gray 30%);"></div> 7 / 10	
Hood <div style="width: 100px; height: 10px; background: linear-gradient(to right, green 70%, gray 30%);"></div> 7 / 10		

Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score



7/10



6,63,584



INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
DOOR HINGES	7	GOOD CONDITION AND WORKING PROPERLY	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
HORN	7	GOOD CONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION AND WORKING PROPERLY	0
HANDBRAKE	7	GOOD CONDITION AND WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION AND WORKING PROPERLY	0
PEDALS	7	GOOD CONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	7	GOOD CONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	7	GOOD CONDITION AND WORKING PROPERLY	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION AND WORKING PROPERLY	0
POWER WINDOWS (YES)	7	GOOD CONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	7	GOOD CONDITION AND WORKING PROPERLY	0



IMAGES



Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score **7/10**



6,63,584

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
CLUTCH PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
ENGINE NOISE	8	NORMAL	0
IGNITION SYSTEM	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	8	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	8	GOOD CONDITION AND WORKING PROPERLY	0
TRANSMISSION ENGAGE	8	GOOD CONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8	GOOD CONDITION AND WORKING PROPERLY	0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

OPTIONAL SPEND EST.

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	(RS)
TYRES	7	GOOD CONDITION AND WORKING PROPERLY	0
SPARE TYRE (YES)	7	GOOD CONDITION AND WORKING PROPERLY	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION AND WORKING PROPERLY	0





 IMAGES

 HOOD


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION AND WORKING PROPERLY	0
WIRING	7	GOOD CONDITION AND WORKING PROPERLY	0
BATTERY	7	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	7	MAXIMUM	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION AND WORKING PROPERLY	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score  **7/10**



6,63,584

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION AND WORKING PROPERLY	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION AND WORKING PROPERLY	0
FOG LAMPS	7	GOOD CONDITION AND WORKING PROPERLY	0
HOOD	6	MINOR SCRATCHES	200
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION AND WORKING PROPERLY	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION AND WORKING PROPERLY	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	6	MINOR SCRATCHES	300
TAIL LIGHT	7	GOOD CONDITION AND WORKING PROPERLY	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION AND WORKING PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0

RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0

Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score **7/10**



6,63,584

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0
BODY RUST	7	GOOD CONDITION	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	8	GOOD CONDITION	0

IMAGES





NEED ATTENTION ⚠





DOCUMENTS



DESCRIPTION

minor scratches

Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score









7/10



6,63,584

IMAGES





Ordered by: Gaurav | Inspected date: 2019-01-14

Order Id: 38495

Overall Score



7/10



6,63,584

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.