



ECO INSPECTION CERTIFICATE

Premium

Order ID : 38562

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Zeeshan Ahmed	Inspection Date : 2019-02-01	Valid Till : 2019-05-01	 Inspected By  Ankit Tomar
-------------------------------	---------------------------------	----------------------------	--

8/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

373+ vehicle inspected
1+ years experience


Um Renegade Commando 280CC, 2017



VEHICLE INFORMATION

MAKE	UM	LOCATION	SAKET
MODEL	RENEGADE COMMANDO	REGISTRATION NO.	DL3SQ3297
YEAR	2017	VIN/CHASIS NUMBER	00216
TRIM	280CC	KMS RUN	25872
COLOR	OTHER	INSURANCE EXPIRY	2020-1-30
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






1,48,439




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre	<div style="width: 80%;"></div>	8 / 10
 Control	<div style="width: 80%;"></div>	8 / 10
 Light	<div style="width: 80%;"></div>	8 / 10
 Oil	<div style="width: 70%;"></div>	7 / 10
 Chassis	<div style="width: 80%;"></div>	8 / 10
 Stand	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score



8/10



1,48,439


TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	8		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	8		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	9		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	9		0

IMAGES



Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score **8/10**




1,48,439

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

IMAGES



CONTROL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	8		0

Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score




8/10



1,48,439

IMAGES





OIL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7		0
LEVELS - HYDRAULIC FLUID (YES)	7		0
LEVELS - COOLANT (YES)	7		0
LEVELS - FUEL	7		0
LEAKS - ENGINE OIL	7		0
LEAKS - GEAR OIL	7		0
LEAKS - HYDRAULIC FLUID	7		0
LEAKS - COOLANT	8		0
LEAKS - FUEL	8		0

IMAGES



Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score **8/10**




1,48,439

LIGHT

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	9		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

IMAGES



Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score



8/10



1,48,439



CHASSIS



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	7		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	9		0



IMAGES



Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score




8/10



1,48,439



DOCUMENTS



DESCRIPTION

found oky

Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score









8/10



1,48,439

 IMAGES



Ordered by: zeeshan ahmed | Inspected date: 2019-02-01

Order Id: 38562

Overall Score



8/10



1,48,439

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.