

ECO INSPECTION CERTIFICATE

Premium

Order ID : 38862

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Tarun	Inspection Date : 2019-01-18	Valid Till : 2019-04-18
-----------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **2** Owners , **8** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ Verified Technician

36+ vehicle inspected
1+ years experience

Pankaj Panwar

Fiat Punto EMOTION PACK 1.4, 2011



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO	REGISTRATION NO.	HRBP3303
YEAR	2011	VIN/CHASIS NUMBER	7031513
TRIM	EMOTION PACK 1.4	KMS RUN	68831
COLOR	OTHER	INSURANCE EXPIRY	2019-1-18
BODY TYPE	HATCHBACK	LOCATION	SEC 15
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (PARTIAL)
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,12,689




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background: yellow;"></div>	6 / 10
Wheel	<div style="width: 60%; background: yellow;"></div>	6 / 10
Test Drive	<div style="width: 70%; background: green;"></div>	7 / 10
Exterior	<div style="width: 60%; background: yellow;"></div>	6 / 10
Hood	<div style="width: 60%; background: yellow;"></div>	6 / 10

TOTAL ESTIMATE SPEND 21,500



Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score



6/10



2,12,689




INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION AND WORKING PROPERLY	0
DOOR HINGES	6	GOOD CONDITION AND WORKING PROPERLY	0
CARPET & FLOOR MAT	6	GOOD CONDITION AND WORKING PROPERLY	0
SEAT & SEAT BELT	6	GOOD CONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD CONDITION AND WORKING PROPERLY	0
HORN	6	GOOD CONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	6	GOOD CONDITION AND WORKING PROPERLY	0
HANDBRAKE	6	GOOD CONDITION AND WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	6	GOOD CONDITION AND WORKING PROPERLY	0
PEDALS	6	GOOD CONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	6	GOOD CONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	6	GOOD CONDITION AND WORKING PROPERLY	0
CUP HOLDERS	6	GOOD CONDITION AND WORKING PROPERLY	0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES)	6	GOOD CONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	6	GOOD CONDITION AND WORKING PROPERLY	0

IMAGES



Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score



6/10



2,12,689

 **NEED ATTENTION** 



 **TEST DRIVE**



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE PERFORMANCE	6	GOOD CONDITION AND WORKING PROPERLY	0
CLUTCH PERFORMANCE	6	GOOD CONDITION AND WORKING PROPERLY	0
ENGINE NOISE	6	NORMAL SOUND	0
IGNITION SYSTEM	6	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	6	GOOD CONDITION AND WORKING PROPERLY	0
TRANSMISSION ENGAGE	6	GOOD CONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (YES)	6	GOOD CONDITION AND WORKING PROPERLY	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

 **IMAGES**



Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score **6/10**




2,12,689

WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD CONDITION AND WORKING PROPERLY	0
SPARE TYRE (YES)	6	NORMAL CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	6	GOOD CONDITION AND WORKING PROPERLY	0

IMAGES



NEED ATTENTION



HOOD

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD CONDITION	0
RH APRON	6	GOOD CONDITION	0
RADIATOR	6	GOOD CONDITION AND WORKING PROPERLY	0
WIRING	6	GOOD CONDITION AND WORKING PROPERLY	0

BATTERY	6	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE FLUID LEVEL	6	MAXIMUM LAVAL	0
ENGINE OIL	7	MAXIMUM LAVAL	0
COOLANT LEVEL	7	MAXIMUM LAVAL	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION AND WORKING PROPERLY	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0

IMAGES



NEED ATTENTION



Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score



6/10



2,12,689

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION AND WORKING PROPERLY	0
FRONT BUMPER	6	MINORS SCRATCHES NEED TO BE REAPING	3000
HEAD LIGHTS	7	GOOD CONDITION AND WORKING PROPERLY	0
GRILLE	7	GOOD	0
TURN SIGNAL	6	GOOD CONDITION AND WORKING PROPERLY	0
FOG LAMPS	6	NOT PROPERLY WORKING NEED TO BE REAPING	500
HOOD	6	GOOD	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD CONDITION AND WORKING PROPERLY	0
LH FENDER	6	GOOD CONDITION	0
LH FRONT DOOR	6	GOOD CONDITION AND WORKING PROPERLY	0
LH REAR DOOR	6	GOOD CONDITION AND WORKING PROPERLY	0
LH RUNNING BOARD	6	NEED TO BE REAPING	4000
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION AND WORKING PROPERLY	0
REAR WINDSHIELD	6	GOOD VISIBILITY AND REAR WIPER CHANG	500
REAR BUMPER	6	NEED TO BE REAPING MINOR SCRATCHES	0
TAIL LIGHT	6	GOOD CONDITION AND WORKING PROPERLY IN AND	0

TRUNK LID/TAIL GATE	6	GOOD CONDITION AND WORKING PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD CONDITION	0
RH QUARTER PANEL	6	MINORS SCRATCHES NEED TO BE REAPING	5000
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION AND WORKING PROPERLY	0

Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score **6/10**




2,12,689

EXTERIOR (CONTINUED)

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	MINORS SCRATCHES	3500
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NEED TO BE REAPING	5000
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD	0

IMAGES



NEED ATTENTION ⚠️





 DOCUMENTS



 DESCRIPTION

minor scratches minor dent and spare tyres need to replace

Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score



6/10



2,12,689

IMAGES





Ordered by: tarun | Inspected date: 2019-01-18

Order Id: 38862

Overall Score



6/10



2,12,689

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.