

ECO INSPECTION CERTIFICATE

Premium

Order ID : 39301

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Aman	Inspection Date : 2019-01-24	Valid Till : 2019-04-24	Inspected By ABHIK CHATTOPADHYAY
----------------------	---------------------------------	----------------------------	--------------------------------------------

9/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
3+ vehicle inspected
1+ years experience

Audi Q3 35 TDI QUATTRO, 2017



VEHICLE INFORMATION			
MAKE	AUDI	TRANSMISSION TYPE	MANUAL
MODEL	Q3	REGISTRATION NO.	WB08D0345
YEAR	2017	VIN/CHASIS NUMBER	WAUZGG8UXGY004066
TRIM	35 TDI QUATTRO	KMS RUN	27037
COLOR	RED	INSURANCE EXPIRY	2019-8-24
BODY TYPE	SEDAN	LOCATION	NEW TOWN
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	3	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE (BUMPER TO BUMPER)	YES
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

30,08,060

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE	
ECO SCORE	TOTAL ESTIMATE SPEND 0
<ul style="list-style-type: none"> Interior 10 / 10 Wheel 9 / 10 Test Drive 9 / 10 Exterior 9 / 10 Hood 9 / 10 	

Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score **9/10**




30,08,060

INTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	9		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	9		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	10		0
PEDALS	9		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	9		0
CUP HOLDERS	9		0
NAVIGATION (YES)	10		0
ODOMETER	10		0
POWER WINDOWS (YES)	9		0
HAZARD LIGHT	10		0

IMAGES



Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score



9/10



30,08,060



NEED ATTENTION



TEST DRIVE




9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9		0
BRAKE PERFORMANCE	9		0
CLUTCH PERFORMANCE	9		0
ENGINE NOISE	9		0
IGNITION SYSTEM	9		0
SUSPENSION PERFORMANCE	9		0
SUSPENSION FRONT SHOCKS	9		0
SUSPENSION REAR SHOCKS	9		0
TRANSMISSION ENGAGE	9		0
CRUISE CONTROL (YES)	9		0
REAR PARKING SENSORS (YES)	10		0
REAR VIEW CAMERA (YES)	9		0



IMAGES



Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score **9/10**



30,08,060

WHEEL

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	9		0
SPARE TYRE (YES)	9		0
WHEEL ASSEMBLY (STEEL RIM)	10		0

IMAGES



NEED ATTENTION



HOOD

9/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	9		0
RADIATOR	10		0
WIRING	10		0
BATTERY	9		0
BRAKE FLUID LEVEL	9		0

ENGINE OIL	9		0
COOLANT LEVEL	9		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	9		0
EXHAUST SYSTEM	10		0

IMAGES



NEED ATTENTION



Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score **9/10**



30,08,060

 **EXTERIOR**

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9		0
FRONT BUMPER	9		0
HEAD LIGHTS	9		0
GRILLE	9		0
TURN SIGNAL	9		0
FOG LAMPS	10		0
HOOD	9		0
PILLAR	10		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	9		0
LH FENDER	10		0
LH FRONT DOOR	9		0
LH REAR DOOR	10		0
LH RUNNING BOARD	9		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	9		0
REAR BUMPER	9		0
TAIL LIGHT	9		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	9		0

Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score



9/10



30,08,060



EXTERIOR (CONTINUED)





9/10







INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	9		0
RH FENDER	9		0
BODY RUST	9	NO DUST	0
ROOF (REGULAR)	10		0
PAINT CONDITION	9	GOOD	0




IMAGES




NEED ATTENTION





 DOCUMENTS



 DESCRIPTION

condition is good

Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score





9/10



30,08,060

 IMAGES





Ordered by: Aman | Inspected date: 2019-01-24

Order Id: 39301

Overall Score



9/10



30,08,060

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.