

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 39542

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Mohit	Inspection Date : 2019-01-28	Valid Till : 2019-05-01	<b>Inspected By</b>   <b>Tej Pratap Yadav</b> Verified Technician 174+ vehicle inspected 1+ years experience
<b>6/10</b>  <b>Overall Score</b>			
<ul style="list-style-type: none"> <li>Evaluated across 5 segments</li> <li>Covered 121+ checkpoints</li> <li>118 does not need attention</li> <li>1 Owner , 4 Years Vehicle Age</li> <li>No Accidental History</li> </ul>			

## Volkswagen Vento 1.5 TDI HIGHLINE AT, 2015



### VEHICLE INFORMATION

MAKE	VOLKSWAGEN	TRANSMISSION TYPE	AUTOMATIC
MODEL	VENTO	REGISTRATION NO.	UP37C5826
YEAR	2015	VIN/CHASIS NUMBER	07695
TRIM	1.5 TDI HIGHLINE AT	KMS RUN	62625
COLOR	OTHER	INSURANCE EXPIRY	2019-1-28
BODY TYPE	SEDAN	LOCATION	NOIDA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	2,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**8,08,481**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior		7 / 10
Wheel		6 / 10
Test Drive		7 / 10
Exterior		7 / 10
Hood		7 / 10

#### TOTAL ESTIMATE SPEND 27,000



Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score



6/10



8,08,481



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD WORKING	0
SPEAKERS & MUSIC SYSTEM	7	GOOD WORKING	0
HANDBRAKE	7	GOOD WORKING	0
STEERING-MOUNTED CONTROLS	7	GOOD WORKING	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD WORKING	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	GOOD CONDITION	0
HAZARD LIGHT	7	GOOD CONDITION	0



## IMAGES



Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score  **6/10**



**8,08,481**

**NEED ATTENTION** ⚠️



**TEST DRIVE**

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD WORKING	0
REAR VIEW CAMERA (YES)	7	GOOD WORKING	0

**IMAGES**



Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score **6/10**



**8,08,481**

## WHEEL


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	6	TIRE WEAR NEED TO BE CHANGE	5000
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0
<b>TYRES</b>	<b>5</b>	<b>FRONT ALL TIRE WEAR NEED TO BE CHANGE</b>	<b>10000</b>

## IMAGES



## NEED ATTENTION



## HOOD

**7/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
<b>BATTERY</b>	<b>6</b>	<b>BATTERY WEEK NEED TO CHARGE</b>	<b>0</b>

BRAKE FLUID LEVEL	7	GOOD CONDITION	0
ENGINE OIL	7	GOOD CONDITION	0
COOLANT LEVEL	7	GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



 NEED ATTENTION 





Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score  **6/10**



**8,08,481**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CUNDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD WORKING	0
FOG LAMPS	7	GOOD WORKING	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	6	MINOR STONE CHEAP MARK	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	6	MINOR SCRATCHES NEED TO BE REPAIR	1000
LH REAR DOOR	6	MINOR SCRATCH NEED TO BE REPAIR	1000
LH RUNNING BOARD	7	GOOD CONDITON	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD CONDITION	0
REAR BUMPER	6	MINOR SCRATCH NEED TO BE REPAIR	1000
TAIL LIGHT	6	L.H.C TAIL LIGHT CRACK MARK NEED TO BE CHANGE	3500
TRUNK LID/TAIL GATE	6	DICKY DENT NEED TO BE REPAIR	1500
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0

RH FENDER	6	MINOR DENT NEEDVTO BE REPAIR	1000
-----------	---	------------------------------	------

Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score **6/10**



**8,08,481**

## EXTERIOR (CONTINUED)

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	GOOD CONDITION	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0
FRONT BUMPER	5	MINOR SCRATCH NEED TO BE REPAIR	1500
GRILLE	4	DEMAGE NEED TO BE CHANGE	1500

## IMAGES




## NEED ATTENTION











## DOCUMENTS



## DESCRIPTION

all body minor scratches metre tempered



Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score




6/10



8,08,481




IMAGES













Ordered by: mohit | Inspected date: 2019-01-28

Order Id: 39542

Overall Score



6/10



8,08,481

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.