

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 39887

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
Vimal

Inspection Date :  
2019-01-30

Valid Till :  
2019-04-30

6/10



Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 105 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Parvesh Kumar

- ✓ Verified Technician
- 3+ vehicle inspected
- 1+ years experience






## Yamaha Ybr 125CC, 2012



### VEHICLE INFORMATION

MAKE	YAMAHA	LOCATION	FARIDABAD
MODEL	YBR	REGISTRATION NO.	HR51AR2089
YEAR	2012	VIN/CHASIS NUMBER	20601
TRIM	125CC	KMS RUN	63753
COLOR	BLACK	INSURANCE EXPIRY	2019-1-30
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	YES (DUPLICATE)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:







14,537




Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Tyre	<div style="width: 60%;"></div>	6 / 10
 Control	<div style="width: 60%;"></div>	6 / 10
 Light	<div style="width: 50%;"></div>	5 / 10
 Oil	<div style="width: 80%;"></div>	8 / 10
 Chassis	<div style="width: 50%;"></div>	5 / 10
 Stand	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 8,500



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score



6/10



14,537


## TYRE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
REAR TYRE CONDITION & AIR PRESSURE	6	GOOD CONDITION	0
WHEEL SPOKES FRONT	6	GOOD CONDITION	0
WHEEL SPOKES REAR	6	GOOD CONDITION	0
WHEEL RIM FRONT	6	GOOD CONDITION	0
WHEEL RIM REAR	6	GOOD CONDITION	0
WHEEL BEARINGS FRONT	6	GOOD CONDITION	0
WHEEL BEARINGS REAR	6	GOOD CONDITION	0
WHEEL SEALS FRONT	6	GOOD CONDITION	0
WHEEL SEALS REAR	6	GOOD CONDITION	0
BRAKE FUNCTION FRONT	6	GOOD CONDITION	0
BRAKE FUNCTION REAR	6	GOOD CONDITION	0
BRAKES CONDITION FRONT	6	GOOD CONDITION	0
BRAKES CONDITION REAR	6	GOOD CONDITION	0
FRONT TYRE CONDITION & AIR PRESSURE	4	NEED TO CHANGE	1500

## IMAGES



Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score



6/10



14,537



NEED ATTENTION



STAND





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	GOOD CONDITION	0
CENTRE STAND RETENTION	6	GOOD CONDITION	0
SIDE STAND CONDITION	6	GOOD CONDITION	0
SIDE STAND RETENTION	6	GOOD CONDITION	0



IMAGES



CONTROL





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	6	GOOD CONDITION	0
PIVOTS	6	GOOD CONDITION	0
CABLES CONDITION	6	GOOD CONDITION	0

CABLES ROUTING	6	PROPER	0
HOSES CONDITION	6	GOOD CONDITION	0
HOSES ROUTING	6	PROPER	0
THROTTLE OPERATION	4	NEED TO CHANGE	250

## IMAGES



## NEED ATTENTION ⚠️



## OIL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	MAXIMUM	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	6	MINIMUM	0
LEAKS - ENGINE OIL	3	ENGINE SIDE OIL LEAKAGE	2000
LEAKS - GEAR OIL	0	NO	0
LEAKS - HYDRAULIC FLUID	0	NO	0
LEAKS - COOLANT	0	NO	0
LEAKS - FUEL	0	NO	0

## IMAGES



Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score  **6/10**




**14,537**

## LIGHT

**5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	GOOD CONDITION	0
BATTERY VENT TUBE	6	GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	6	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	6	PROPER WORKING	0
TURN SIGNALS OPERATION FRONT RIGHT	6	GOOD CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	6	GOOD CONDITION	0
SWITCHES OPERATION	6	GOOD CONDITION	0
MIRRORS CONDITION	6	GOOD CONDITION	0
MIRRORS AIM	6	GOOD	0
WIRING CONDITION	6	GOOD CONDITION	0
WIRING ROUTING	6	PROPER	0
HEADLAMP CONDITION	3	BROKEN	800
TURN SIGNALS OPERATION FRONT LEFT	3	NOT WORKING	150
TURN SIGNALS OPERATION REAR LEFT	4	NOT WORKING PROPER	200
LENSES & REFLECTORS CONDITION	4	BROKEN	100

## IMAGES



Ordered by: Vimal | Inspected date: 2019-01-30



Order Id: 39887

Overall Score  **6/10**



**14,537**

 **NEED ATTENTION** 



 **CHASSIS**

**5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME STEERING-HEAD BEARINGS	6	GOOD CONDITION	0
FRAME SWINGARM BUSHINGS	6	GOOD CONDITION	0
SUSPENSION FRONT FORKS LEFT	6	GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	6	GOOD CONDITION	0
FASTENERS THREADED	6	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	6	GOOD CONDITION	0
ENGINE	6	GOOD CONDITION	0
FRAME CONDITION	2	RUESTD	2000
CHAIN/BELT TENSION	3	BED CONDITION	0
CHAIN/BELT LUBRICATION	3	NO LUBRICATION	0
CHAIN/BELT SPROCKETS	3	NEED TO CHANGE	500
TRANSMISSION	3	CHAIN SET NEED TO CHANGE	1000



Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score



6/10



14,537

**IMAGES**



**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**

all body normal scratches rear tire already changed normal engine sound chain set need to change fr

Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score




6/10



14,537

IMAGES



Ordered by: Vimal | Inspected date: 2019-01-30

Order Id: 39887

Overall Score



6/10



14,537

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.