

ECO INSPECTION CERTIFICATE

Premium

Order ID : 40468

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Krishana	Inspection Date : 2019-02-09	Valid Till : 2019-05-11	Inspected By Verified Technician 187+ vehicle inspected 1+ years experience Tej Pratap Yadav
--------------------------	---------------------------------	----------------------------	---

7/10

Overall Score

- Evaluated across 6 segments
- Covered 121+ checkpoints
- 118 does not need attention
- 2 Owners , 2 Years Vehicle Age
- No Accidental History

Um Renegade Commando 280CC, 2017



VEHICLE INFORMATION

MAKE	UM	LOCATION	DELHI
MODEL	RENEGADE COMMANDO	REGISTRATION NO.	DL13SU1945
YEAR	2017	VIN/CHASIS NUMBER	302718
TRIM	280CC	KMS RUN	3461
COLOR	OTHER	INSURANCE EXPIRY	2019-2-9
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,44,198




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 70%;"></div>	7 / 10
Control	<div style="width: 70%;"></div>	7 / 10
Light	<div style="width: 70%;"></div>	7 / 10
Oil	<div style="width: 80%;"></div>	8 / 10
Chassis	<div style="width: 70%;"></div>	7 / 10
Stand	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score **7/10**




1,44,198

TYRE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
WHEEL SPOKES FRONT	7	GOOD CONDITION	0
WHEEL SPOKES REAR	7	GOOD CONDITION	0
WHEEL RIM FRONT	7	GOOD CONDITION	0
WHEEL RIM REAR	7	GOOD CONDITION	0
WHEEL BEARINGS FRONT	7	GOOD CONDITION	0
WHEEL BEARINGS REAR	7	GOOD CONDITION	0
WHEEL SEALS FRONT	7	GOOD CONDITION	0
WHEEL SEALS REAR	7	GOOD CONDITION	0
BRAKE FUNCTION FRONT	7	GOOD CONDITION	0
BRAKE FUNCTION REAR	7	GOOD CONDITION	0
BRAKES CONDITION FRONT	7	GOOD CONDITION	0
BRAKES CONDITION REAR	7	GOOD CONDITION	0

IMAGES



Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score **7/10**



1,44,198

NEED ATTENTION




STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	GOOD CONDITION	0
CENTRE STAND RETENTION	7	GOOD CONDITION	0
SIDE STAND CONDITION	7	GOOD CONDITION	0
SIDE STAND RETENTION	7	GOOD CONDITION	0

IMAGES



NEED ATTENTION



CONTROL



7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	7	GOOD CONDITION	0
PIVOTS	7	GOOD CONDITION	0
CABLES CONDITION	7	GOOD CONDITION	0
CABLES ROUTING	7	GOOD CONDITION	0
HOSES CONDITION	7	GOOD CONDITION	0
HOSES ROUTING	7	GOOD CONDITION	0
THROTTLE OPERATION	7	GOOD CONDITION	0



IMAGES



NEED ATTENTION



OIL




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	GOOD CONDITION	0

LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	7	GOOD CONDITION	0
LEAKS - ENGINE OIL	7	GOOD CONDITION	0
LEAKS - FUEL	7	GOOD CONDITION	0
LEAKS - GEAR OIL	0	N/A	0
LEAKS - HYDRAULIC FLUID	0	N/A	0
LEAKS - COOLANT	0	N/A	0

IMAGES



Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score **7/10**



1,44,198

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	AVERAGE	0
BATTERY VENT TUBE	7	GOOD CONDITION	0
HEADLAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	7	GOOD CONDITION	0
TURN SIGNALS OPERATION FRONT LEFT	7	GOOD CONDITION	0
TURN SIGNALS OPERATION FRONT RIGHT	7	GOOD CONDITION	0
TURN SIGNALS OPERATION REAR LEFT	7	GOOD CONDITION	0
TURN SIGNALS OPERATION REAR RIGHT	7	GOOD CONDITION	0
SWITCHES OPERATION	7	GOOD CONDITION	0
MIRRORS CONDITION	7	GOOD CONDITION	0
MIRRORS AIM	7	GOOD CONDITION	0
LENSES & REFLECTORS CONDITION	7	GOOD CONDITION	0
WIRING CONDITION	7	GOOD CONDITION	0
WIRING ROUTING	7	GOOD CONDITION	0

IMAGES



Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score **7/10**



1,44,198

NEED ATTENTION



CHASSIS

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7	GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	7	GOOD CONDITION	0
FRAME SWINGARM BUSHINGS	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS LEFT	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	7	GOOD CONDITION	0
CHAIN/BELT TENSION	7	GOOD CONDITION	0
CHAIN/BELT LUBRICATION	7	GOOD CONDITION	0
CHAIN/BELT SPROCKETS	7	GOOD CONDITION	0
FASTENERS THREADED	7	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	7	GOOD CONDITION	0
ENGINE	7	GOOD CONDITION	0
TRANSMISSION	7	GOOD CONDITION	0

Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score



7/10



1,44,198


IMAGES



NEED ATTENTION



DOCUMENTS



DESCRIPTION

all body minor scratches

Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score














7/10



1,44,198

IMAGES



Ordered by: Krishana | Inspected date: 2019-02-09

Order Id: 40468

Overall Score



7/10



1,44,198



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.