

ECO INSPECTION CERTIFICATE

Premium

Order ID : 41504

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Shiv	Inspection Date : 2019-02-12	Valid Till : 2019-05-12	Inspected By Verified Technician 216+ vehicle inspected 1+ years experience Aabid Ali
<h2>8/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> Evaluated across 5 segments Covered 121+ checkpoints 120 does not need attention 1 Owner , 1 Year Vehicle Age No Accidental History 	

Mahindra Kuv100 Nxt K8 D 6 STR DUAL TONE, 2018



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	KUV100 NXT	REGISTRATION NO.	DL10CK5588
YEAR	2018	VIN/CHASIS NUMBER	L90620
TRIM	K8 D 6 STR DUAL TONE	KMS RUN	1740
COLOR	BLACK	INSURANCE EXPIRY	2019-2-19
BODY TYPE	SUV	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	40,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)
		SERVICE LOGS AVAILABLE	YES (FULL)
		BANK HYPOTHECATION	YES
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

7,93,346

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
Interior	<div style="width: 80%;"></div> 8 / 10	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> </div> <div style="display: flex; justify-content: space-around; margin-top: 10px;"> Interior Wheel Test Drive Exterior Hood </div>
Wheel	<div style="width: 80%;"></div> 8 / 10	
Test Drive	<div style="width: 80%;"></div> 8 / 10	
Exterior	<div style="width: 80%;"></div> 8 / 10	
Hood	<div style="width: 80%;"></div> 8 / 10	

Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score **8/10**



7,93,346

INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
NAVIGATION (YES)	8	GOOD	0
ODOMETER	8	GOOD	0
POWER WINDOWS (YES)	8	GOOD	0
HAZARD LIGHT	8	GOOD	0
CUP HOLDERS	0	NA	0

IMAGES



Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score **8/10**



7,93,346

NEED ATTENTION ⚠️




TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	8	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0
CRUISE CONTROL (YES)	8	GOOD	0
REAR PARKING SENSORS (YES)	8	GOOD	0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score



8/10



7,93,346

WHEEL




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	8	GOOD	0

IMAGES



NEED ATTENTION ⚠



HOOD




8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	8	GOOD	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	8	GOOD	0

ENGINE OIL	8	GOOD	0
COOLANT LEVEL	8	GOOD	0
BRAKE & COOLANT HOSE PIPES	8	GOOD	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

IMAGES



NEED ATTENTION



Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score  **8/10**



7,93,346

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	8	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	8	GOOD	0
TAIL LIGHT	8	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOOD	0

Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score



8/10



7,93,346



EXTERIOR (CONTINUED)



8/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD	0
RH FENDER	8	GOOD	0
BODY RUST	8	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	8	GOOD	0



IMAGES




NEED ATTENTION





 DOCUMENTS



 DESCRIPTION

Overall good condition vehicle

Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score









8/10



7,93,346

IMAGES





Ordered by: Shiv | Inspected date: 2019-02-12

Order Id: 41504

Overall Score



8/10



7,93,346

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.