

ECO INSPECTION CERTIFICATE

Premium

Order ID : 42732

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Devendra

Inspection Date :
2019-02-20

Valid Till :
2019-05-20

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 1 Owner , 12 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Sagar Chavan

- ✓ Verified Technician
- 28+ vehicle inspected
- 1+ years experience

Mercedes-Benz S-Class 350 L, 2007



VEHICLE INFORMATION

MAKE	MERCEDES-BENZ	TRANSMISSION TYPE	AUTOMATIC
MODEL	S-CLASS	REGISTRATION NO.	DL09CQ3389
YEAR	2007	VIN/CHASIS NUMBER	WDD2211566L001585
TRIM	350 L	KMS RUN	63022
COLOR	OTHER	INSURANCE EXPIRY	2018-12-22
BODY TYPE	SEDAN	LOCATION	WORLI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

17,15,255




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 1,58,500



Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score



6/10



17,15,255



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	NO DAMAGE	0
DOOR HINGES	6	NO DAMAGE	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	6	NO DAMAGE	0
HORN	6	GOOD SOUND	0
HANDBRAKE	6	WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	6	NO DAMAGE	0
PEDALS	6	WORKING CONDITION	0
CENTRAL LOCK	6	NO DAMAGE	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	NO DAMAGE	0
POWER WINDOWS (YES)	6	WORKING PROPERLY	0
HAZARD LIGHT	6	WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	4	NON WORKING	20000



IMAGES



Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score



6/10



17,15,255



NEED ATTENTION



TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	ACCEPTABLE	0
CLUTCH PERFORMANCE	6	ACCEPTABLE CONDITION	0
ENGINE NOISE	6	NORMAL	0
IGNITION SYSTEM	6	ACCEPTABLE	0
SUSPENSION PERFORMANCE	6	ACCEPTABLE	0
SUSPENSION FRONT SHOCKS	6	ACCEPTABLE CONDITION	0
SUSPENSION REAR SHOCKS	6	ACCEPTABLE CONDITION	0
TRANSMISSION ENGAGE	6	AUTOMATIC	0
CRUISE CONTROL (YES)	6	WORKING PROPERLY	0
REAR PARKING SENSORS (YES)	4	REPAIR REQUIRE	20000
REAR VIEW CAMERA (YES)	4	NON WORKING	30000



IMAGES



Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score **6/10**




17,15,255

WHEEL


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	ACCEPTABLE TREAD	0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	6	NO DAMAGE	0

IMAGES



NEED ATTENTION ⚠




HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NO DAMAGE	0
RH APRON	6	NO DAMAGE	0
RADIATOR	6	WORKING CONDITION	0
WIRING	6	NO DAMAGE	0
BATTERY	6	ACCEPTABLE CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM	0

COOLANT LEVEL	6	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	6	NO DAMAGE	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	WORKING PROPERLY	0
ENGINE OIL	5	NEW REQUIRE	20000

IMAGES



Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score  **6/10**



17,15,255

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	6	WORKING CONDITION	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	6	WORKING CONDITION	0
FOG LAMPS	6	WORKING PROPERLY	0
PILLAR	6	NO DAMAGE	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
SIDE VIEW MIRRORS	6	WORKING PROPERLY	0
LH FENDER	6	NO DAMAGE	0
LH FRONT DOOR	6	DENT NOT AVAILABLE	0
LH REAR DOOR	6	NO SCRATCHES	0
LH RUNNING BOARD	6	NO DAMAGE	0
FUEL LID	6	WORKING PROPERLY	0
REAR WINDSHIELD	6	NO CRACKED	0
TAIL LIGHT	6	WORKING PROPERLY	0
TRUNK LID/TAIL GATE	6	NO DAMAGE	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD SPACE	0
RH RUNNING BOARD	6	NO DAMAGE	0
RH REAR DOOR	6	NO DENTS AVAILABLE	0
RH FRONT DOOR	6	SCRATCHES NOT AVAILABLE	0
RH FENDER	6	NO DAMAGE	0
BODY RUST	6	NOT AVAILABLE	0
ROOF (SUN ROOF)	6	WORKING PROPERLY	0
PAINT CONDITION	6	GOOD	0
LICENSE PLATE	4	NEW REQUIRE	3500

Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score **6/10**



17,15,255

EXTERIOR (CONTINUED)


6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	4	PAINTING REQUIRE	10000
HOOD	4	SYMBOL NOT AVAILABLE	25000
LH QUARTER PANEL	4	PAINTING REQUIRE	10000
REAR BUMPER	4	PAINTING REQUIRE	10000
RH QUARTER PANEL	4	PAINTING REQUIRE	10000

IMAGES




NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

acceptable condition car but engine oil leak. repair cost 1,00,000

Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score









6/10



17,15,255

IMAGES





Ordered by: Devendra | Inspected date: 2019-02-20

Order Id: 42732

Overall Score



6/10



17,15,255

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.