

ECO INSPECTION CERTIFICATE

Premium

Order ID : 42794

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Abdul	Inspection Date : 2019-02-19	Valid Till : 2019-05-20
-----------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 2 Owners , 8 Years Vehicle Age
- ✓ No Accidental History

Inspected By

✓ **Verified Technician**

5+ vehicle inspected

1+ years experience

Aditya Singh

Ford Figo Duratorq Zxi 1.4, 2011



VEHICLE INFORMATION

MAKE	FORD	TRANSMISSION TYPE	MANUAL
MODEL	FIGO	REGISTRATION NO.	UP32DW1129
YEAR	2011	VIN/CHASIS NUMBER	MAJ1XXMRJ1B178565
TRIM	DURATORQ ZXI 1.4	KMS RUN	60200
COLOR	WHITE	INSURANCE EXPIRY	2019-6-22
BODY TYPE	HATCHBACK	LOCATION	LUCKNOW
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,79,819




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 30,500



Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score  **6/10**




1,79,819

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7		0
HAZARD LIGHT	7		0

IMAGES



Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score **6/10**



1,79,819

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	6		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score  **6/10**



1,79,819

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0

Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score **6/10**



1,79,819

EXTERIOR (CONTINUED)


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6		0
ROOF (REGULAR)	6		0
FOG LAMPS	3	BROKEN	2000
RH RUNNING BOARD	3	DENT EXISTS	3500
PAINT CONDITION	5	SCRATCHES AVAILABLE	25000

IMAGES



NEED ATTENTION ⚠️



Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score




6/10



1,79,819



DOCUMENTS



DESCRIPTION

good car but need some maintenance

Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score














6/10



1,79,819

IMAGES



Ordered by: abdul | Inspected date: 2019-02-19

Order Id: 42794

Overall Score



6/10



1,79,819

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.