


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 42850

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ishan	Inspection Date : 2019-02-19	Valid Till : 2019-05-19	Inspected By  Manoj Kumar
-----------------------	---------------------------------	----------------------------	--

## 7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 2 Owners , 9 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**  
398+ vehicle inspected  
1+ years experience

## Ford Endeavour 3.0L 4X4 AT, 2010



### VEHICLE INFORMATION

MAKE	FORD	TRANSMISSION TYPE	AUTOMATIC
MODEL	ENDEAVOUR	REGISTRATION NO.	HR26BE9225
YEAR	2010	VIN/CHASIS NUMBER	44097
TRIM	3.0L 4X4 AT	KMS RUN	47361
COLOR	BLACK	INSURANCE EXPIRY	2020-1-1
BODY TYPE	SUV	LOCATION	PALAM VIHAR
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**5,97,313**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 6,900



Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score  **7/10**




**5,97,313**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	7	GOOD	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NA	0

## IMAGES



Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score  **7/10**



**5,97,313**

**NEED ATTENTION**



**TEST DRIVE**

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	7	GOOD	0

**IMAGES**



Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score  **7/10**



**5,97,313**

## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

## IMAGES




## HOOD

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

## IMAGES



NEED ATTENTION



Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score  **7/10**



**5,97,313**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	6	MINOR SCTATCHES	300
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	6	MINOR SCRATCHES	300
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	6	MINOR SCRATCHES	300
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	6	MINOR SCRATCHES	500
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	6	MINOR SCRATCHES	500
RH FRONT DOOR	6	MINOR SCRATCHES	500

Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score  **7/10**



**5,97,313**

## EXTERIOR (CONTINUED)

**7/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	MINOR SCRATCHES	500
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
REAR BUMPER	4	NEED TO REPAIR	4000

## IMAGES





## NEED ATTENTION ⚠️





 DOCUMENTS





## DESCRIPTION

minor scratches and minor dent all tyres already changed

Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score


















7/10



5,97,313

IMAGES





Ordered by: ishan | Inspected date: 2019-02-19

Order Id: 42850

Overall Score



7/10



5,97,313

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.