




ECO INSPECTION CERTIFICATE

Premium

Order ID : 43644

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : VICKY	Inspection Date : 2019-02-21	Valid Till : 2019-05-21	 Inspected By  Verified Technician 168+ vehicle inspected 1+ years experience Pawan Kumar Gupta
<div style="text-align: center;"> <h2>7/10</h2>  <p>Overall Score</p> </div> <ul style="list-style-type: none"> ✓ Evaluated across 5 segments ✓ Covered 121+ checkpoints ✓ 121 does not need attention ✓ 1 Owner , 3 Years Vehicle Age ✓ No Accidental History 			

Maruti Suzuki Alto 800 LXI, 2016



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	ALTO 800	REGISTRATION NO.	PB10FY5023
YEAR	2016	VIN/CHASIS NUMBER	3330
TRIM	LXI	KMS RUN	7175
COLOR	WHITE	INSURANCE EXPIRY	2019-5-23
BODY TYPE	HATCHBACK	LOCATION	LUDHIANA
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	6,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLEN	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	YES
		 BANK NOC	NO









Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

2,32,139



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
 Interior	<div style="width: 70%;"><div style="width: 70%;"></div></div> 7 / 10	<div style="text-align: center;">0</div>  <div style="display: flex; justify-content: space-around; font-size: small;"> Interior Wheel Test Drive Exterior Hood </div>
 Wheel	<div style="width: 60%;"><div style="width: 60%;"></div></div> 6 / 10	
 Test Drive	<div style="width: 80%;"><div style="width: 80%;"></div></div> 8 / 10	
 Exterior	<div style="width: 70%;"><div style="width: 70%;"></div></div> 7 / 10	
 Hood	<div style="width: 70%;"><div style="width: 70%;"></div></div> 7 / 10	

Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score  **7/10**





2,32,139

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	SAFE	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	WELL	0
DASHBOARD & INSTRUMENT PANEL	6	WORKING	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	WORKING	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	WELL	0
PEDALS	7	SAFE	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	WORKING	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	WORKING	0

IMAGES



Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score **7/10**



2,32,139

NEED ATTENTION



TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	7	WELL	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	LESS NOISE	0
IGNITION SYSTEM	7	SMOOTH	0
SUSPENSION PERFORMANCE	7	SAFE	0
SUSPENSION FRONT SHOCKS	7	SAFE	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	SMOOTH	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score **7/10**



2,32,139

WHEEL




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

IMAGES



NEED ATTENTION ⚠️



HOOD



7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	SAFE	0
WIRING	7	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	7	ABOVE AVERAGE	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	ABOVE AVERAGE	0
BRAKE & COOLANT HOSE PIPES	7	SAFE	0
UNDERCARRIAGE	7	BETTER	0
EXHAUST SYSTEM	7	BETTER	0

IMAGES



NEED ATTENTION



Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score  **7/10**



2,32,139

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	NO DAMAGE	0
FRONT BUMPER	7	NO DAMAGE	0
HEAD LIGHTS	6	WORKING	0
GRILLE	6	GOOD	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	7	WORKING	0
HOOD	7	SAFE	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	7	NO SCRATCHES	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	7	SAFE	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	NO DAMAGE	0
LH QUARTER PANEL	7	SAFE	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	SAFE	0
REAR BUMPER	7	NO DAMAGE	0
TAIL LIGHT	6	WORKING	0
TRUNK LID/TAIL GATE	7	SAFE	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	7	SAFE	0
RH RUNNING BOARD	6	NO DAMAGE	0
RH REAR DOOR	7	GOOD	0

Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score



7/10



2,32,139



EXTERIOR (CONTINUED)



7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	SAFE	0
RH FENDER	7	GOOD	0
BODY RUST	7	NO BODY RUST	0
ROOF (REGULAR)	7	SMOOTH	0
PAINT CONDITION	7	GOOD	0




IMAGES



NEED ATTENTION





 DOCUMENTS



 DESCRIPTION

good

Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score















7/10



2,32,139

IMAGES





Ordered by: VICKY | Inspected date: 2019-02-21

Order Id: 43644

Overall Score



7/10



2,32,139

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.