

ECO INSPECTION CERTIFICATE

Premium

Order ID : 43922

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Pavan

Inspection Date : 2019-03-10

Valid Till : 2019-06-10

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 102 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Sagar Chavan

- ✓ Verified Technician
- 71+ vehicle inspected
- 1+ years experience

Hyundai I20 ASTA 1.2, 2011



VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	I20	REGISTRATION NO.	MH01BB3843
YEAR	2011	VIN/CHASIS NUMBER	MALBB51BLBM344157
TRIM	ASTA 1.2	KMS RUN	63358
COLOR	BLACK	INSURANCE EXPIRY	2020-1-24
BODY TYPE	HATCHBACK	LOCATION	KALACHOWKI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (DUPLICATE)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,06,193




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 90,200



Ordered by: Pavan | Inspected date: 2019-03-10

Order Id: 43922

Overall Score



6/10



3,06,193



INTERIOR








6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	ACCEPTABLE CONDITION	0
DOOR HINGES	6	ACCEPTABLE	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	NEW SEAT COVER REQUIRE	5000
DASHBOARD & INSTRUMENT PANEL	6	WORKING CONDITION	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	WORKING CONDITION	0
HANDBRAKE	6	WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	6	ACCEPTABLE CONDITION	0
PEDALS	6	WORKING CONDITION	0
CENTRAL LOCK	6	WORKING PROPERLY	0
A/C VENTS & HEATER	6	ACCEPTABLE CONDITION	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	NO DAMAGE	0
POWER WINDOWS (YES)	6	WORKING CONDITION	0
HAZARD LIGHT	6	WORKING CONDITION	0



IMAGES






TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	ACCEPTABLE	0
CLUTCH PERFORMANCE	6	ACCEPTABLE CONDITION	0
ENGINE NOISE	6	MINIMUM	0
IGNITION SYSTEM	6	WORKING CONDITION	0
TRANSMISSION ENGAGE	6	SMOOTHLY TRANSFER	0
CRUISE CONTROL (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
SUSPENSION PERFORMANCE	4	NEW REQUIRE	15000
SUSPENSION FRONT SHOCKS	5	NEED TO REPLACE	10000
SUSPENSION REAR SHOCKS	5	NEED TO REPLACE	5000
REAR PARKING SENSORS (YES)	4	NEED TO REPLACE	3000



IMAGES






WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	ACCEPTABLE CONDITION	0
SPARE TYRE (YES)	6	NO DAMAGE	0
WHEEL ASSEMBLY (ALLOY RIM)	6	NO DAMAGE	0

 IMAGES






 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NO DAMAGE	0
RH APRON	6	NO DAMAGE	0
RADIATOR	6	NO DAMAGE	0
WIRING	6	NO DAMAGE	0
BATTERY	6	ACCEPTABLE CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM	0
ENGINE OIL	6	ACCEPTABLE CONDITION	0
COOLANT LEVEL	6	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	6	NO DAMAGE	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	WORKING PROPERLY	0

 IMAGES





Ordered by: Pavan | Inspected date: 2019-03-10

Order Id: 43922

Overall Score  **6/10**



3,06,193

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	6	WORKING CONDITION	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	6	ALL ARE WORKING CONDITION	0
FOG LAMPS	6	ACCEPTABLE CONDITION	0
PILLAR	6	ACCEPTABLE CONDITION	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
LH RUNNING BOARD	6	ACCEPTABLE CONDITION	0
FUEL LID	6	WORKING PROPERLY	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
TAIL LIGHT	6	WORKING	0
TRUNK LID/TAIL GATE	6	ACCEPTABLE CONDITION	0
RH FRONT DOOR	6	ACCEPTABLE CONDITION	0
BODY RUST	6	NOT AVAILABLE	0
PAINT CONDITION	6	REPAINTING REQUIRE	20000
LICENSE PLATE	5	NEW REQUIRE	1000
FRONT BUMPER	4	NEED TO PAINTING	2500
HOOD	4	SRATCHES AVAILABLE	2000
SIDE VIEW MIRRORS	3	MIRROR GLASS REQUIRE	200
LH FENDER	4	SCRATCHES AVAILABLE	2000
LH FRONT DOOR	4	NEED TO PAINTING	2500
LH REAR DOOR	4	PAINTING REQUIRE	2500
LH QUARTER PANEL	5	PAINTING REQUIRE	2500
REAR BUMPER	4	PAINTING REQUIRE	2500
LUGGAGE COMPARTMENT LIGHT	5	REPAIR & ACCEPTABLE SPACE	2000

Ordered by: Pavan | Inspected date: 2019-03-10

Order Id: 43922

Overall Score



6/10



3,06,193



EXTERIOR (CONTINUED)




5/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	3	PAINTING REQUIRE	2500
RH RUNNING BOARD	5	PAINTING REQUIRE	2500
RH REAR DOOR	4	PAINTING REQUIRE	2500
RH FENDER	4	PAINTING REQUIRE	2500
ROOF (REGULAR)	4	DENT AVAILABLE	2500




IMAGES



 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

acceptable car condition but repaint require

Ordered by: Pavan | Inspected date: 2019-03-10

Order Id: 43922

Overall Score





6/10



3,06,193

IMAGES





Ordered by: Pavan | Inspected date: 2019-03-10

Order Id: 43922

Overall Score



6/10



3,06,193

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.