

ECO INSPECTION CERTIFICATE

Premium

Order ID : 44216

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ravi	Inspection Date : 2019-02-24	Valid Till : 2019-05-24	Inspected By Sikandar Shariff
----------------------	---------------------------------	----------------------------	--------------------------------------

8/10
Overall Score

- Evaluated across 6 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 1 Owner , 6 Years Vehicle Age
- No Accidental History

Verified Technician
3+ vehicle inspected
1+ years experience

Royal Enfield Classic 350CC, 2013



VEHICLE INFORMATION			
MAKE	ROYAL ENFIELD	LOCATION	BEGUR, BLR
MODEL	CLASSIC	REGISTRATION NO.	PB65X3815
YEAR	2013	VIN/CHASIS NUMBER	ME3U3S5C0EA367352
TRIM	350CC	KMS RUN	2651
COLOR	OTHER	INSURANCE EXPIRY	2019-3-29
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be: **1,05,907**

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
Tyre	8/10	0
Control	8/10	0
Light	8/10	0
Oil	8/10	0
Chassis	8/10	0
Stand	8/10	0

www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score



8/10



1,05,907

TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	8		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	8		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

IMAGES



Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score **8/10**



1,05,907

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

IMAGES



CONTROL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	7		0

Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score




8/10



1,05,907

IMAGES





OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8		0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7		0
LEVELS - HYDRAULIC FLUID (YES)	8		0
LEVELS - COOLANT (YES)	8		0
LEVELS - FUEL	8		0
LEAKS - ENGINE OIL	8		0
LEAKS - GEAR OIL	8		0
LEAKS - HYDRAULIC FLUID	8		0
LEAKS - COOLANT	8		0
LEAKS - FUEL	8		0

IMAGES



Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score



8/10



1,05,907


 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	7		0
HEADLAMP CONDITION	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

 IMAGES



Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score



8/10



1,05,907



CHASSIS




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	7		0
CHAIN/BELT LUBRICATION	7		0
CHAIN/BELT SPROCKETS	7		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	8		0
TRANSMISSION	8		0



IMAGES



Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score




8/10



1,05,907



DOCUMENTS



DESCRIPTION

Vehicle is in good condition

Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score





8/10



1,05,907

IMAGES



Ordered by: ravi | Inspected date: 2019-02-24

Order Id: 44216

Overall Score



8/10



1,05,907

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.