

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 45881

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
ASHISH

Inspection Date :  
2019-02-28

Valid Till :  
2019-06-03

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 114 does not need attention
- ✓ 2 Owners , 9 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Ashish  
Aggarwal

- ✓ Verified Technician
- 88+ vehicle inspected
- 1+ years experience

## Fiat Punto EMOTION PACK 1.4, 2010



### VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO	REGISTRATION NO.	DL7CK7251
YEAR	2010	VIN/CHASIS NUMBER	484KNZ
TRIM	EMOTION PACK 1.4	KMS RUN	70394
COLOR	RED	INSURANCE EXPIRY	2019-4-3
BODY TYPE	HATCHBACK	LOCATION	GURUGRAM
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

1,83,876




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div></div>	7 / 10
Wheel	<div></div>	7 / 10
Test Drive	<div></div>	7 / 10
Exterior	<div></div>	7 / 10
Hood	<div></div>	7 / 10

#### TOTAL ESTIMATE SPEND 3,000





Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score



7/10



1,83,876



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION	0
HANDBRAKE	7	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD CONDITION	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	GOOD CONDITION	0
HAZARD LIGHT	7		0
NAVIGATION (YES)	0	NA	0



## IMAGES





Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score



7/10



1,83,876



## TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0



## IMAGES



## WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD CONDITION	0



## IMAGES




## HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	GOOD CONDITION	0
ENGINE OIL	7	GOOD CONDITION	0
COOLANT LEVEL	7	GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

## IMAGES









Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score



7/10



1,83,876



EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION	0
FOG LAMPS	7	GOOD CONDITION	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD CONDITION	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD CONDITION	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0



Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score



7/10



1,83,876



## EXTERIOR (CONTINUED)




7/10





INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7		0
LH FENDER	4	NEED PAINT	1500
RH QUARTER PANEL	5	NEED TO PAINT	1500
BODY RUST	0	NA	0




## IMAGES









## NEED ATTENTION



## DOCUMENTS



## DESCRIPTION







Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score




7/10











1,83,876

IMAGES









Ordered by: ASHISH | Inspected date: 2019-02-28

Order Id: 45881

Overall Score



7/10



1,83,876



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.