



ECO INSPECTION CERTIFICATE

Premium

Order ID : 47693

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Devesh	Inspection Date : 2019-03-13	Valid Till : 2019-06-13	 Inspected By  Ankur Ankur
------------------------	---------------------------------	----------------------------	--


6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **116** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**
23+ vehicle inspected
1+ years experience

Skoda Fabia AMBIENTE 1.2 TDI, 2010



VEHICLE INFORMATION			
MAKE	SKODA	TRANSMISSION TYPE	MANUAL
MODEL	FABIA	REGISTRATION NO.	UP32DK9806
YEAR	2010	VIN/CHASIS NUMBER	TMBAEH5J5AG014346
TRIM	AMBIENTE 1.2 TDI	KMS RUN	43000
COLOR	SILVER	INSURANCE EXPIRY	2019-11-2
BODY TYPE	SEDAN	LOCATION	LUCKNOW
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	YES (DUPLICATE)
 DENT	NO	 INSURANCE COPY AVAILABLE	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:






1,91,854




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, gray 40%);"></div>	6 / 10
 Wheel	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, gray 40%);"></div>	6 / 10
 Test Drive	<div style="width: 70%; background: linear-gradient(to right, green 70%, gray 30%);"></div>	7 / 10
 Exterior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, gray 40%);"></div>	6 / 10
 Hood	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, gray 40%);"></div>	6 / 10

TOTAL ESTIMATE SPEND 52,500



Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score  **6/10**





1,91,854

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0

IMAGES



Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score **6/10**





1,91,854

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
CLUTCH PERFORMANCE	3	VERY HARD	8000
ENGINE NOISE	3	BAD	20000

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score  **6/10**



1,91,854

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
HEAD LIGHTS	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0

Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score  **6/10**



1,91,854

 EXTERIOR (CONTINUED) 


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6		0
ROOF (REGULAR)	6		0
FRONT BUMPER	3	SCRATCHES	2500
GRILLE	1	BROKEN	2000
PAINT CONDITION	4	SCRATCHES	20000

 IMAGES



 NEED ATTENTION 



Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score




6/10



1,91,854



DOCUMENTS



DESCRIPTION

need maintenance

Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score




6/10



1,91,854

IMAGES



Ordered by: Devesh | Inspected date: 2019-03-13

Order Id: 47693

Overall Score



6/10



1,91,854

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.