

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 50571

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Priyanshu	Inspection Date : 2019-03-15	Valid Till : 2019-06-15
---------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **111** does not need attention
- ✔ **2** Owners , **12** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ Verified Technician

138+ vehicle inspected  
1+ years experience

Kishan Kumar

## Hyundai Getz Prime 1.1 Gvs, 2007



### VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	GETZ PRIME	REGISTRATION NO.	DL3CBF0550
YEAR	2007	VIN/CHASIS NUMBER	61082
TRIM	1.1 GVS	KMS RUN	77609
COLOR	OTHER	INSURANCE EXPIRY	2019-3-15
BODY TYPE	HATCHBACK	LOCATION	GHAZIABAD
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

93,588




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%; background: yellow;"></div>	6 / 10
Wheel	<div style="width: 60%; background: yellow;"></div>	6 / 10
Test Drive	<div style="width: 60%; background: yellow;"></div>	6 / 10
Exterior	<div style="width: 60%; background: yellow;"></div>	6 / 10
Hood	<div style="width: 60%; background: yellow;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 14,400



Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score



6/10



93,588



## INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR CONDITION	0
DOOR HINGES	6	FAIR CONDITION	0
CARPET & FLOOR MAT	6	FAIR CONDITION	0
SEAT & SEAT BELT	6	FAIR CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR CONDITION	0
HORN	7	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	FAIR MUSIC	0
HANDBRAKE	6	FAIR CONDITION	0
PEDALS	6	FAIR CONDITION	0
CENTRAL LOCK	6	FAIR CONDITION	0
A/C VENTS & HEATER	6	FAIR COOLING	0
CUP HOLDERS	6	FAIR CONDITION	0
ODOMETER	6	FAIR CONDITION	0
POWER WINDOWS (YES)	6	FAIR CONDITION	0
HAZARD LIGHT	6	FAIR CONDITION	0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0



## IMAGES



Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score



**6/10**



**93,588**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BRAKE PERFORMANCE	6	FAIR CONDITION	0
IGNITION SYSTEM	6	FAIR CONDITION	0
SUSPENSION PERFORMANCE	6	FAIR CONDITION	0
SUSPENSION FRONT SHOCKS	6	FAIR CONDITION	0
TRANSMISSION ENGAGE	6	FAIR CONDITION	0
STEERING PERFORMANCE	5	STEERING HARD NEED TO CHECK AND REPAIR	1000
CLUTCH PERFORMANCE	5	CLUTH HARD NEED TO CHECK AND REPAIR	4000
ENGINE NOISE	5	ENGINE NOISE NEED TO CHECK AND REPAIR	2500
SUSPENSION REAR SHOCKS	5	BOTH SUSPENSION DAME NEED TO CHANGE	3800
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0


## IMAGES



## WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	FAIR CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	FAIR CONDITION	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR CONDITION	0
RH APRON	6	FAIR CONDITION	0
RADIATOR	6	FAIR CONDITION	0
WIRING	6	FAIR CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	FAIR CONDITION	0
ENGINE OIL	6	FAIR VISCOSITY	0
COOLANT LEVEL	6	MINIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	FAIR CONDITION	0
UNDERCARRIAGE	6	FAIR CONDITION	0
EXHAUST SYSTEM	6	FAIR CONDITION	0

 IMAGES



Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score



6/10



93,588

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR CONDITION	0
FRONT BUMPER	7	DENT AND SCRATCHES AND BUMPER NEED TO BE REPAIR	2000
HEAD LIGHTS	6	FAIR CONDITION	0
GRILLE	6	FAIR CONDITION	0
TURN SIGNAL	6	FAIR CONDITION	0
HOOD	6	FAIR CONDITION	0
PILLAR	6	FAIR CONDITION	0
FRONT WINDSHIELD	6	FAIR CONDITION	0
SIDE VIEW MIRRORS	6	FAIR CONDITION	0
LH FENDER	6	SCRATCHES	0
LH FRONT DOOR	6	FAIR CONDITION	0
LH REAR DOOR	6	FAIR CONDITION	0
LH RUNNING BOARD	6	FAOR CONDITION	0
LH QUARTER PANEL	6	FAIR CONDITION	0
FUEL LID	6	FAIR CONDITION	0
REAR WINDSHIELD	6	FAIR CONDITION	0
REAR BUMPER	6	SCRATCHES	400
TAIL LIGHT	6	FAIR CONDITION	0
TRUNK LID/TAIL GATE	6	FAIR CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR CONDITION	0
RH QUARTER PANEL	6	FAIR CONDITION	0
RH RUNNING BOARD	6	FAIR CONDITION	0
RH REAR DOOR	6	SCRATCHES	400
RH FRONT DOOR	6	SCRATCHES	300

Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score  **6/10**



**93,588**

**EXTERIOR (CONTINUED)**


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	FAIR CONDITION	0
BODY RUST	6	FAIR CONDITION	0
ROOF (REGULAR)	6	FAIR CONDITION	0
PAINT CONDITION	6	FAIR CONDITION	0
FOG LAMPS	0	NA	0


**IMAGES**



## NEED ATTENTION



## DOCUMENTS



## DESCRIPTION

All body scratches and dent need to repair and service due cluth hard and engine noise check and ne



Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score






6/10



93,588

IMAGES





Ordered by: Priyanshu | Inspected date: 2019-03-15

Order Id: 50571

Overall Score



6/10



93,588

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.